

REPORT of SURVEY for REPAIRS, &c.

45832

No. 14 Survey held at London Date, First Survey 18th Dec 85 Last Survey 1 Feb 1886
 No. in Reg. Book. 14 on the S Camaran Master J Maxwell
 Received in London Office, SAT 6 FEB 1886

TONNAGE:—
 NET 1306 Built at Greenock By whom Scott & Co When 1874
 GROSS 1364 Owners Shaw Savill & Albion Co Port belonging to Glasgow
 UNDER DE. 1166 Owner's Address _____

If Surveyed Afloat or in Dry Dock _____ Name of Dock Poplar Dry Dock Destined Voyage New Zealand

Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 44119 Port London Classed _____
 Character in Register Book. 100 A 1, 8, 84
SS Gls No 2, 84

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard in salt water _____ ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in fresh water _____ ft. ins.
 of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE
At present placed in the Dry Dock
The Bottom cleaned examined and coated.


PRESENT CONDITION OF THE							
Decks	<u>Good</u>	Plank (Bottom) & Counter	<u>Good</u>	Ceiling	<u>Good</u>	Boats	<u>Good</u>
Waterways	"	Freeboards or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	<u>From DH</u>
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	<u>Good</u>
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors No. of <u>8 Nos. 12 & 2 Nos</u>	
Planksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Wat'rways	"	Cables <u>Parten DH</u>	<u>Good</u>
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"
Topsides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"
Wales	"					Hatches	"
Engine Room Skylights	<u>u</u>	Coal Bunker, Openings, Lids, &c.	<u>u</u>	Scuppers <u>Good</u>		Cargo & Main Hatchways	<u>Good</u>

General Observations, Opinion as to Class, &c.:
She is now in an efficient state
and eligible to remain as classed

Senhouse Martindale

Entry Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	} received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute _____
 Character assigned 100 A 1

Surveyor to Lloyd's Register of British & Foreign Shipping.

 Lloyd's Register Foundation
 LONG 76-0456

If a Steam Ship, state whether or not a Report is also sent on the Machinery.

Insert Character precisely as in Register Book.

Form No. 2 for Repairs. The Surveyors are requested not to write on or below the space for Committee's Minute.

Assam


REPORT OF SURVEY FOR THE YEAR 1903

Assam

No. _____

By _____

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2021
 Lloyd's Register
 Foundation