

45847

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

TUESDAY 9 FEB 1886

No. 45847
No. in Survey held at London Date, first Survey 29 Dec Last Survey 1886
Reg. Book. 63 on the Machinery of the "St. Oceano" (Number of Visits 1)
Tonnage, Gross 1004 Built at Middlesbro When built 1871
Ditto, Net 650 Owners Tatham & Co Port belonging to London
Diameter of Cylinder 27 Engines made by F. Richardson & Co When made 1871
Length of Stroke 33 Boilers made by i When made 1871
Pressure of Steam 70 If Surveyed Afloat or in Dry Dock River Character in Register Book. 100 A1
Registered Horse Power 100 (State Name of Dock.)
Last Survey No. 45267 Port Lon LMC 1182 BS 884

Particulars of Repairs and Examination

Boiler repairs & survey.

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined main double ended boiler & found it in a good condition. A crack in one of the furnaces has been cut out and patched. A bulge in the same furnace has been bulged out.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The machinery of this vessel is in a safe working condition & eligible in my opinion to have the notification B. S. 12. 85 recorded in the Register Book

Office or Registration Fee (per Sec. 27)	£	:	:
Survey Fee (per Section 28)	£	1	1
Special Damage Fee (per Section 28)	£	:	:
*Certificate (if required)	£	:	:
Travelling Expenses (if chargeable)	£	:	:

received by me, Y.B.W.
13/2/1886

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Assigned

FRIDAY 12 FEB 1886



Lloyd's Register Foundation

LON576-0473

State if a Report is also sent on the Hull of the Ship

* Certificate to be sent to

Form No. 9—Transfer Ink—2000, 27/7/85.

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that this vessel
is eligible to have the notification
B.S. 12.85 recorded the
boilers being subject to
resurvey as per rule.

W.P.

8/2/85



© 2021

Lloyd's Register
Foundation