

No. 45852

No. in Reg. Book. 202

Survey held at London

Date, First Survey 9th July Last Survey 20th July 1886

on the Steel S.S. "Manora"

Master W. Cosens

TONNAGE:—

NET 3040

GROSS 4707

UNDER DEK 1863

Built at Dumbarton

By whom Jm Denny & Co

When 1883

12

Owner's Messrs Gray, Dawes & Co

Port belonging to London

Owner's Address

If Surveyed Afloat or in Dry Dock afloat

Name of Dock R. Albert & Co

Destined Voyage India

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

Classed Underwritten Registry A1*1

Last Survey, No. 45423

Port Yon

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship

in salt water

ft.

ins.

in fresh water

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE As requested Examined this Vessel and found her in very good condition. We find that she has 6 web frames fitted in the Tween Decks as shown and now marked in blue on the Midship Section, thus fulfilling the Committee's requirements. 13 Hold Beam Stanchions 3 3/4" diam. have now been fitted to the Hold Beams, and the remainder are to be fitted on the Vessel's return. We have also had the midship section corrected by Mr Dutton under whose survey she was built, and his letter we herewith attach - fully shewing the web frames in the Engine and Boiler spaces which we found fitted.

CONDITION OF THE	Plank (Bottom) & Counter	Ceiling	Boats
Good	Good	Good	6 & Steam Launch, good
Trunnels or Rivets	Good	Rudder	Masts, Yards, &c. good
Breasthooks and Stemson	—	Windlass & Capstan	Condition, how ascertained from deck
Transoms, Pointers, & Crutches	—	Pumps	Sails good
Timbers of Frame at the openings	—	Cement (if Iron Ship)	Anchors No. of 4 B. 15. 3 H.
ditto ditto at other places	—	Caulking of Bot'm, D'k, & Wat'rways	Cables good
Keelsons	—	Copper or V.M.	Hawseers & Warps 13", 11", 9" and one 6"
Clamps & Shells	—	(State if on Felt.)	Standing & Running Rigging good
When put on	—	When put on	Good
Engine Room Skylights	Coal Bunker, Openings, Lids, &c. Good	Scuppers Good	Cargo & Main Hatchways Good
Hatches	Good		

General Observations, Opinion as to Class, &c.: Then the remainder of the Hold Beam pillars are fitted we are of opinion she will be eligible to be classed as A1

Entry Fee (if chargeable) per Scale I., Sec. 27. £ : : : received by me, 188

Office Fee (if chargeable) per Scale I., Sec. 27. £ : : :

Survey Fee (per Section 28) £ : : :

Special Damage Fee (if any) (per Sec. 28) £ : : :

*Certificate (if required) to be sent as per margin £ : : :

Travelling Expenses (if chargeable) £ : : :

Surveyor's Fee (if any) £ : : :

Surveyor's Minute

Character assigned

FRIDAY 12 FEB 1886

Wm C. Dancy

Char. H. Dancy

Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register Foundation

LON 676-0478