

46097

Report of Survey for Repairs, &c., of Engines & Boilers.

No. _____ (Received at London Office, _____)

No. in Reg. Book. Survey held at London Date, first Survey 19 March Last Survey _____ 1886

100 on the Machinery of the Nellie Wise (Number of Visits _____)

Tonnage, Gross 1058 Built at W Hartlepool Year _____ Month _____

Ditto, Net 680 Owners North Atlantic SS Co When built 1873

Diameter of Cylinder 27 1/4 Engines made by Blair & Co When made 1873

Length of Stroke 33 Boilers made by _____ When made 1873

Pressure of Steam ? If Surveyed Afloat or in Dry Dock Sheffield Docks Character in Register Book. A1

Registered Horse Power 110 Classed 1st

Last Survey No. _____ Port _____

Particulars of Repairs and Examination Annual

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Lucas & connections found
them good.

It is submitted that this vessel is eligible to remain as classed
M 27/4/86

General Observations, Opinion, and Recommendation:— As far as seen the
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)
machinery of this vessel is in a safe working
condition eligible in my opinion to remain as
classed.

Office or Registration Fee (per Sec. 27)	£	:	:	} received by me, <u>188</u>
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (per Section 28)	£	:	:	
*Certificate (if required)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	

O. J. Shearn
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute _____
Assigned _____
FRIDAY 30 APRIL 1886