

46171

Report of Survey for Repairs, &c., of Engines & Boilers.

No.

(Received at London Office)

TUESDAY 18 MAY 1886

No. in
Reg. Book.

Survey held at

London

Date, first Survey

11 May

Last Survey

1886

653

on the Machinery of the

S. S. Grecian

Monarch

(Number of Visits

1

Year Month

Tonnage, Gross

4364

Built at

Hull

When built

1882 5

Ditto, Net

2832

Owners

Royal Exchange S Co

Port belonging to

London

Diameter of Cylinder

43 86

Engines made by

Charles Co

When made

1882

Length of Stroke

60

Boilers made by (i)

When made

1882

Pressure of Steam

80

If Surveyed Afloat or in Dry Dock

Mullwall Dock

Classed

100 A1

Registered Horse Power

530

6.85

Last Survey No.

Port

+ L. M. C. 3.82

Particulars of Repairs and Examination

Seacocks & Connections

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Seacocks & Connections & found them good.

New propeller blades have been fitted.

The Special survey will be held later on in this year when the Sailors will be drawn

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Machinery of this vessel is in a safe working condition and eligible in my opinion to remain as classed.

Office or Registration Fee (per Sec. 27)

£

:

:

Survey Fee (per Section 28)

£

:

:

Special Damage Fee (per Section 28)

£

:

:

Certificate (if required)

£

:

:

Travelling Expenses (if chargeable)

£

:

:

received by me,
188


Committee's Minute

FRIDAY 21 MAY 1886

Assigned

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

C. J. Bromeyer



Lloyd's Register
Foundation

46171-0334