

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office, _____)

No. _____
 No. in Survey held at London Date, first Survey and Last Survey June 8 1886
 Reg. Book. _____
 on the Machinery of the S. S. "Norham Castle" (Number of Visits 1)
300 Year _____ Month _____
 Tonnage, Gross 4 241 Built at Glasgow When built 1883-2
 Ditto, Net 2722 Owners D. Currie & Co Port belonging to London
 Diameter of Cylinder 50 x 90 Engines made by J. Elder & Co When made 1883
 Length of Stroke 60 Boilers made by Do. When made 1883
 Pressure of Steam 80 lbs. ~~Is~~ Surveyed Afloat or in Dry Dock Green's Character in Register Book. _____
 Registered Horse Power 600 (State Name of Dock.) _____
 Last Survey No. _____ Port _____ Classed 100 A 1
L.M.C. 583.

Particulars of Repairs and Examination For Annual Survey.

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Vessel placed in dry dock, sea connections examined & found to be in good condition. Propeller disconnected tail shaft (hollow steel) drawn, examined, found in good condition, the stern bush relined & propeller replaced. Thrust & tunnel shafting examined & found in good condition

*It is submitted that
 this vessel is eligible
 to remain as classed
 M 9/6/86*

General Observations, Opinion, and Recommendation :--

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

appears eligible to remain as classed.

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ : :
 Special Damage Fee (per Section 28) £ : :
 *Certificate (if required) £ : :
 Travelling Expenses (if chargeable) £ : :

received by me,
 188

Geo. E. Mickelson.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Assigned



© 2021

Lloyd's Register
 Foundation

4540-LE9N07