

Report of Survey for Repairs, &c., of Engines & Boilers.

No. ~~46472~~ Port of ~~London~~ Date, first Survey ~~13 April~~ Last Survey ~~21 May~~ 1886
No. in Reg. Book. ~~707~~ Survey held at ~~London~~ on the Machinery of the ~~SS Egyptian Monarch~~ (Number of Visits ~~2~~ ^{vis})
Tonnage, Gross ~~3970~~ Built at ~~Mill~~ When built ~~1880~~ 8
Ditto, Net ~~2608~~ Owners ~~Royal Exchange S.C.~~ Port belonging to ~~London~~
Diameter of Cylinder ~~46 87~~ Engines made by ~~Farley Co.~~ When made ~~1880~~
Length of Stroke ~~57~~ Boilers made by ~~0~~ When made ~~1880~~
Pressure of Steam ~~80~~ If Surveyed Afloat or in Dry Dock ~~Chellwall Dr~~ Classified ~~100 A1~~
Registered Horse Power ~~500~~ (State name of Dock.)
Last Survey No. ~~745~~ Port ~~N. Yk~~ + L. M. C. 10. 80.

Particulars of Repairs and Examination ~~Completion of Special Survey~~
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined crankshaft, Low pressure cylinder & High pressure slide and the inside of the Boilers and found them in a good condition. The safety valves were found to blow off at 80 lb.

For remainder of Survey see London report No 45648 dated 2nd to 5th Oct 1885.

General Observations, Opinion, and Recommendation:— The Special Survey on this vessel being now completed it is submitted that this vessel is eligible to have the notification L. M. C. 4. 86 recorded in the Register Book.

Office or Registration Fee (per Sec. 27) £ — : — :
Survey Fee (per Section 28) £ 5 : 5 :
Special Damage Fee (per Section 28) £ — : — :
Certificate (if required) £ — : 5 :
Travelling Expenses (if chargeable) £ — : — :
Committee's Minute
Assigned
FRIDAY 27 AUGUST 1886
S. S. No 4 86

received by me, 1st Sept 1886
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.
© 2021 Lloyd's Register Foundation

It is submitted that this vessel
is eligible to have the notification
Smb 14.86 recorded

W.F.
25/8/86