

46566

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office, THURS. 9 SEPT 1886)

No. 423 Port of London
 No. in Reg. Book. 423 Survey held at London Date, first Survey and Last Survey Sept 7 1886
 on the Machinery of the S. S. "Sisbon" (Number of Visits 1 Year Month)
 Tonnage, Gross 1334 Built at W. Horsfield When built 1871-7
 Ditto, Net 860 Owners J. Hall jun. & Co. Port belonging to London
 Diameter of Cylinder 27 1/2 Engines made by Blair & Co. When made 1871
 Length of Stroke 36 Boilers made by Do. When made 1871
 Pressure of Steam 10 lbs. If Surveyed Afloat or in Dry Dock Aft. Lon. Docks Classed 100 A1.
 Registered Horse Power 120 (State Name of Dock.) Character in Register Book. 6.86
 Last Survey No. M.S. 11.82. B.S. 85. Port 6.86

Particulars of Repairs and Examination For S. S. "Sisbon"
 (State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined cylinders, slides, air, circulating feed and bilge pumps, & found them in good condition.
Crane & Thrust shaft examined.
For report on Boilers see London report No 46281 dated June 1886.

General Observations, Opinion, and Recommendation:— The machinery being now in good & safe working condition renders the vessel eligible in my opinion to be marked in the Register Book with B + M. S. 9. 86 provided that the boilers are again examined within 12 mths. as per rule.
 (State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)


Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ : :
 Special Damage Fee (per Section 28) £ : :
 *Certificate (if required) £ : :
 Travelling Expenses (if chargeable) £ : :

received by me, 6/10/86

Geo. E. Merriamson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUESDAY 28 SEPT 1886

Assigned B. S. A. 16



State if a repair is made on the hull of the ship

Insert Character of Ship and Machinery precisely as in the Register Book.

2678-0292

It is submitted that this vessel
is eligible to have the
notification B RMS 6.86
recorded the boilers being
subject to resurvey as
per Rule and the Sea Connections
in dry dock

W.P.
9/9/86.

~~W.P.~~

