

Report of Survey for Repairs, &c., of Engines & Boilers.

No. _____ Port of _____
No. in Survey held at London Date, first Survey Aug. 26 Last Survey Sept. 29 1886
Reg. Book. _____ on the Machinery of the S. S. "The Lady Carmichael" (Number of Visits 8)
212 Year _____ Month _____
Tonnage, Gross 369 Built at Dumbarton When built 1871-3
Ditto, Net 194 Owners Submarine Tel. Co. Port belonging to London
Diameter of Cylinder 34 Engines made by J & J. Thomson When made 1871
Length of Stroke 48 Boilers made by _____ When made 1879
Pressure of Steam 30 If Surveyed Afloat or in Dry Dock W. Stokes & Co. D. & A. & Co. Character in Register Book. 90A1
Registered Horse Power 165 Classified _____
Last Survey No. _____ Port _____ L.M.C.G. 84 B.S.G. 86.

Particulars of Repairs and Examination Of Boilers

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

The Main boilers have been lifted out of the vessel, the defective parts at backs, under the bottom, & combustion chambers have been cut out & new plates fitted, & new screwed stays throughout the bottom, seventeen new stays in steam space renewed. -
Boilers tested with hydraulic pressure after repairs to 60 lbs & & safety valves set under steam to 30 lbs & i. Engines & Boilers tried under steam & found to be satisfactory.

General Observations, Opinion, and Recommendation :--

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

good & safe working condition renders the vessel eligible in my opinion to remain as classed & have the notification B. S. G. 86 recorded, provided that the boilers are again examined within 12 mths. as per rule.

Office or Registration Fee (per Sec. 27) £ : : -
Survey Fee (per Section 28) £ 3 : 3 : -
Special Damage Fee (per Section 28) £ 1 : - : -
*Certificate (if required) £ - : 2 : 6
Travelling Expenses (if chargeable) £ : : -

£3-5/6
received by me,
26/10/1886

A.C.C.

Geo. E. Milnerison.

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUESDAY 12 OCT 1886

Assigned

B. S. G. 86



© 2021

Lloyd's Register Foundation

LON 678-0349

It is submitted that this vessel
is eligible to have the notification
BS 9.86 recorded the boilers
being subject to resurvey as
per Rule

W.F.
11/10/86



© 2021

Lloyd's Register
Foundation