

46759

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office) THURS NOV 18 1886

No. in Reg. Book. *378* Survey held at *London* Port of *London* Date, first Survey *and* Last Survey *Nov 9 1886*
on the Machinery of the *S. S. "Catanina"* (Number of Visits *1*)
Tonnage, Gross *2198* Built at *Glasgow* When built *1881-11*
Ditto, Net *1429* Owners *Aust. S. S. Co. Ltd.* Port belonging to *Hamburg*
Diameter of Cylinder *35 & 65* Engines made by *A. Stephen & Sons* When made *1881*
Length of Stroke *42* Boilers made by *Do.* When made *1881*
Pressure of Steam *80 lbs.* If Surveyed Afloat or in Dry Dock *L. S. H. & D. Dr.* Classified *100A1*
Registered Horse Power *200*
Last Survey No. *LMC. 9. 85.* Port *LMC. 9. 85.*

Particulars of Repairs and Examination For Annual Survey -

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Vessel placed in dry dock, sea connections examined & found to be in good condition, the propeller & its connections sound & the tail shaft a good working fit in Stern bush.

General Observations, Opinion, and Recommendation:— *As far as seen this vessel appears eligible to remain as classed.*


Office or Registration Fee (per Sec. 27).....	£	:	:
Survey Fee (per Section 28)	£	✓	✓
Special on Damage, Fee (per Section 28)	£	:	:
*Certificate (if required) to be sent as per margin..	£	:	:
Travelling Expenses (if chargeable)	£	:	:

received by me, 188

Geo. E. Milner
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *TUESDAY NOV 23 1886*

Assigned



It is submitted that this vessel is
eligible to remain as classed

W.F.

19/11/86

