

REPORT of SURVEY for REPAIRS, &c.

No. 46837 London Date, First Survey 16th Jan'y Last Survey 19th Nov 1886

SS Walton Built at Sunderland By whom Short Bros. When 1877 Owners Charles C Barton Port belonging to London

Last Survey, No. 18271 Port New

REPAIRS, OR EXAMINATION AS PER RULE Special Survey No 2 & Change of Owners. At the present time the vessel placed in the dry dock the bottom cleaned, examined and coated. All the timbers and ceiling taken off the top of double bottom in the Main after and Fore holds, and the Man hole doors removed, the double bottom cleaned, and examined and found good, and the cement adhering well to the iron, and where worn has been thickened and repaired. Double Bottom tested up to above light line & quite tight. Indented plate made fair on Portside & new built ship to do this. Chain cables ranged on deck and examined good. Iron Windlass in good condition. The Beam Pillars named in the Newcastle Report No 18271 have been repaired & put in the places. This vessel has been laid up since last January.

PRESENT CONDITION OF THE		Boats	
Decks (Iron)	Good	Boats	Good
Waterways	"	Masts, Yards, &c.	"
Comings	"	Condition, how ascertained	Examined
Up'r Dk. Beams & Fastenings	"	Sails	Good
Low'r Dk. Beams & Fastenings	"	Anchors	No. of 3 Nos. 11 & 12 Nos
Planksheers	"	Cables	Complete
Sheerstrakes	"	Hawsers & Warps	"
Topsides	"	Standing & Running Rigging	"
Wales	"	Hatches	"
Engine Room Skylights	Good	Coal Bunker, Openings, Lids, &c.	Good
General Observations, Opinion as to Class, &c.:	She is now in an efficient state and eligible to remain as classed, and to have SS London No 2-1886, recorded in the Register Book.		

Surveyor to Lloyd's Register of British & Foreign Shipping. L. M. B. 11 86 FRIDAY 17 DEC 1886

Beyn



© 2021

Lloyd's Register
Foundation