

# REPORT of SURVEY for REPAIRS, &c.

No. 46839

Port of London

Received in London Office, FRIDAY 17 DEC 1883

No. in Reg. Book. Survey held at London

Date, First Survey 13/12/83 Last Survey 13/12/83

455 on the British Queen

By whom Don Sps.

Master Mills YEAR 86 MONTH 12

TONNAGE:-

Built at Belfast

By whom Richard May

NET 2277

GROSS 3558

Owners British Shipowners Co Ltd

Port belonging to Liverpool

UNDER DECK 3254

Owner's Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Name of Dock

Tilbury

Destined Voyage

Calicut

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft. ins.

(If these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Classed

100A1 3-86

Last Survey, No. 45997 Port Lon

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer 7 ft. 6 ins. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in Winter 7 ft. 11 ins. of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition

This vessel was seen in the Tilbury Drying dock, bottom examined cleaned & coated. New Stock supplied to Spare Power Anchor.

The chain cables ranged out for inspection 300 fathoms in length.

## PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			Hatches
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel was appears now, to be in a sound and efficient condition, eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£
Office Fee (if chargeable) per Scale II., Sec. 27...	£
Survey Fee (per Section 28) .....	£ 1 10
Special on Damage, Fee (if any) (per Sec. 28)....	£
*Certificate (if required) to be sent as per margin	£
Travelling Expenses (if chargeable) .....	£
Second Surveyor's Fee (if any) .....	£

Fees received by me,

3-1-1884

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUESDAY 21 DEC 1883

Character assigned

100A1



Lloyd's Register Foundation