

REPORT of SURVEY for REPAIRS, &c.

No. 46868 Port of London Date, First Survey 10th Dec Last Survey 13th Dec 1886

Survey held at on the SS Arena Master A Tegner

Built at Sunderland By whom Larison Owners Rederi Bol arena. W Thornhousmer Port belonging to Oddervalla

TONNAGE: NET 521 GROSS 747 UNDER DECK 548

If Surveyed Afloat or in Dry Dock Name of Dock Commercial Dry Dock Destined Voyage Sunderland

Length of Poop ft. of Forecastle ft. of Raised Or. Deck ft. of Moulded Depth

Last Survey, No. 18745 Port Nive SS Nive, 1885

REPAIRS, OR EXAMINATION AS PER RULE Damage Repairs.

At present placed in the dry dock the bottom cleaned examined and coated.

Portside at Midship Bilges, 3 broken plates renewed, 1 plate indented taken off made fair and replaced

11 frames slightly fractured compensated for by additional frame angle iron back to back. One fractured floor doubled.

Starboard Bilge 1 New plate.

ceiling taken up in way of damage and the cement cut out, the cement renewed and the ceiling relaid.

PRESENT CONDITION OF THE Decks Waterways Comings Up'r Dk. Beams & Fastenings Low'r Dk. Beams & Fastenings Plank sheers Sheerstrakes Topsides Wales Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo & Main Hatchways Hatches



N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.



© 2021

Lloyd's Register  
Foundation