

# REPORT of SURVEY for REPAIRS, &c.

47082

THURS 17 MARCH 1887

No.

Port of London

No. in Reg. Book.

Survey held at

Millwall

Date, First Survey

(No. of Visits)

Last Survey

1887

on the *SS "Gracie"*

TONNAGE:—

NET

894

GROSS

1394

UNDERDECK

1167

Built at *Hartlepool*

By whom

*W. H. H. H.*

Owners

*S. Clarke & Co*

Owner's Address

(if not already recorded in Appendix to Register Book.)

Master *J. Brown*

YEAR.

MONTH.

When

1879

9

Port belonging to

*London*

If Surveyed Afloat or in Dry Dock

Name of Dock

*Outer Millwall*

Destined Voyage

*Coast*

Length of Poop

ft.:

of Forecastle

ft.:

of Raised Or. Deck

(if these particulars are not yet recorded in the Register Book.)

ft.: Moulded Depth

ft.

ins.

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No.

*46260*

Port

*Lon*

Classed

*100 A1*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship

in Summer

ft.

ins.

in Winter

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Damage*

*Stem new Except 14 ft lower End. Ten bow plates on the starboard side and 11 on the Port side new. 3 bow frames wholly renewed and one about half renewed. Starboard Hawse pipe refitted 3 Angle bars between frames to upper Deck stringer new and one piece of angle bar on each side to lower stringer. 5-deck planks in forecastle, and one piece of loway each side cut 14 ft long. 6 planks of lower forecastle Deck and 6 of platform. Decks from forecastle sills forward painted new work repainted Cables ranged*

*Port of Damage - Bottom repainted.*

PRESENT CONDITION OF THE

Decks

*Good*

Plank (Bottom) & Counter

*Good*

Ceiling

*Good*

Boats

*Good*

Waterways

Comings

Up'r Dk. Beams & Fastenings

Low'r Dk. Beams & Fastenings

Plank sheers

Sheerstrakes

Topsides

Wales

Engine Room Skylights

*Good*

Coal Bunker, Openings, Lids, &c.

*Good*

Scuppers

*Good*

Cargo & Main Hatchways

*Good*

Hatches

*Good*

General Observations, Opinion as to Class, Recommendation, &c.:

*She is now in good condition and in my opinion eligible to continue as Classed*

Entry Fee (if chargeable) per Scale I., Sec. 27...

£

Office Fee (if chargeable) per Scale II., Sec. 27...

£

Survey Fee (per Section 28) .....

£

Special on Damage, Fee (if any) (per Sec. 28)....

£

\*Certificate (if required) to be sent as per margin

£

Travelling Expenses (if chargeable) .....

£

Second Surveyor's Fee (if any) .....

£

Fees received by me, 19/3/1887

*W. H. H. H.*

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUESDAY 22 MARCH 1887

Character assigned

*100 A1*