

Report of Survey for Repairs, &c., of Engines & Boilers.

No. _____ (Received at London Office, _____)

No. in Reg. Book. Survey held at London Date, first Survey Apr. 28 Last Survey Apr. 29 1887

487 on the Machinery of the S. S. "Palmyra" (Number of Visits 2)

Tonnage, Gross 760 Built at Newcastle When built 1866-1

Ditto, Net 707 Owners J. Fenwick & Son Port belonging to London

Diameter of Cylinder 25" x 48" Engines made by P. & W. Hawthorn When made 1866

Length of Stroke 30 Boilers made by _____ When made 1872

Pressure of Steam 75 lbs. ☒ Surveyed Afloat or in Dry Dock Smith's (State name of Dock.)

Registered Horse Power 140 Character in Register Book. 90A1

Classed 90A1

Last Survey No. _____ Port _____ By M.S. 3.85

Particulars of Repairs and Examination In Annual Survey

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Vessel placed in dry dock sea connections examined & found to be in good condition, the propeller & its fastenings sound & the tail shaft down 3" in Stern bush

Examined donkey boiler, & safety valves found to be in good condition, & loaded with a dead weight valve to 35 lbs.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

appears eligible to remain as classed


Office of Registration Fee (per Sec. 27)	£	:	:	} received by me, <u>188</u>
Survey Fee (per Section 28)	£	✓	✓	
Special Damage Fee (per Section 28)	£	:	:	
*Certificate (if required)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	

Committee's Minute FRIDAY 13 MAY 1887

Assigned B. S. H. J. C. B.

W. H. H.

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

 Lloyd's Register Foundation

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character of Ship and Machinery precisely as in the Register Book.

LON 680-0108

It is submitted that this vessel
is eligible to have the notification
B.S. 11.86 recorded.

DP

2/5/87

