

# REPORT of SURVEY for REPAIRS, &c.

47337

No. 47331

Port of London

Received in London Office, TUESDAY 14 JUNE 1887

No. in Reg. Book

Survey held at London

Date, First Survey 12<sup>th</sup> May Last Survey 14<sup>th</sup> May 1887

(No. of Visits)

Master W. Wartin

293

on the Iron Ship "Ataki".

TONNAGE :-

Built at Newcastle By whom Palmers & Co. When 1875. 8

NET 10.14

Owners New Zealand Shipping Co. Port belonging to Lyttelton, N.Z.

GROSS 10.53

Owners' Address (if not already recorded in Appendix to Register Book.)

UNDER DK. 555

If Surveyed Afloat or in Dry Dock Dry Name of Dock West India Destined Voyage Lyttelton N.Z.

Length of Poop ft. : of Forecastle ft. : of Raised Or. Deck ft. : Moulded Depth ft. ins. Character in Register Book

Classed 100 A1

Last Survey, No. 46524 Port London S.S. No. 1-79. 7-85

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) of any letters respecting this case. ) as painted on Ship

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

The bottom outside was examined and found in good condition, it has been cleaned and coated. The rudder has been overhauled and the pintles rebushed.

This vessel was examined for S.S. No. 2. and reported in in March 1884. But I understand the fees have not been paid.

PRESENT CONDITION OF THE		Plank (Bottom) & Counter		Ceiling	Boats
Decks	Good	Good	Good	Good	Good
Waterways	✓	Treenails or Rivets	✓	Rudder	✓
Comings	✓	Breasthooks & Stems	✓	Windlass & Capstan	✓
Up'r Dk. Beams & Fastenings	✓	Transoms, Painters, & Crutches	✓	Pumps	✓
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the openings	✓	Cement (If Iron Ship)	✓
Planksheers	✓	Ditto ditto at other places	✓	Caulking of Bot'm, D'k, & Watrways	✓
Sheerstrakes	✓	Keelsons	✓	Copper, or Y.M. (State if on Felt.) When put on	✓
Topsides	✓	Clamps & Shelves	✓		
Wales	✓				
Engine Room Skylights	Good	Coal Bunker, Openings, Lids, &c.	Good	Scuppers	Good
				Cargo & Main Hatchways	Good
				Hatches	✓

General Observations, Opinion as to Class, Recommendation, &c. :

This vessel now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28) .....	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28) ....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable) .....	£	:	:	
Second Surveyor's Fee (if any) .....	£	:	:	

Allison B. Wilson. Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 17 JUNE 1887 Character assigned 100 A1



If a Steam Ship, state particularly whether or not a Report is also sent on the Machinery

Insert Character precisely as in Register Book.

8220-089207