

47368

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 47368 Port of London (Received at London Office, *)
 No. in Survey held at London Date, first Survey July 25th Last Survey 9th May 1887
 Reg. Book 3985 on the Machinery of the S. S. Glenavon (Number of Visits 5)
 Year Month

Tonnage, Gross 2985 Built at Glasgow When built 1881 2
 Ditto, Net 1936 Owners M. Glyn & Co Port belonging to Glasgow
 Diameter of Cylinder 48+88 Engines made by London & Glas Co When made 1881
 Length of Stroke 52 Boilers made by " When made 1881
 Pressure of Steam " If Surveyed Afloat or in Dry Dock Afloat (State Name of Dock.)
 Registered Horse Power 530 Classed 100A1
 Last Survey No. 46659 Port Low 2 MC 985

Particulars of Repairs and Examination Annual survey
 (State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)


Examined main boiler inside & out & found them generally in good condition. defective parts in furnaces cut out and bottoms calked as required.
Safety valves examined and found good
Donkey boiler in good order - same retubed.
Safety valve examined and found in good working order.
All the boilers are said to have been tested by hydraulic pressure in compliance with a Board of Trade request.

General Observations, Opinion, and Recommendation: -- The machinery of this vessel, as far as seen, is now in good order & eligible in our opinion to remain as classed with the record B. S. 587 in the Register Book
 (State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ 2 : 2 : 0
 Special on Damage, Fee (per Section 28) £ : :
 *Certificate (if required) to be sent as per margin.. £ : :
 Travelling Expenses (if chargeable) £ : :

received by me, John Waller & Co }
27.6.1887 }
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUESDAY 28 JUNE 1887
 Assigned J.M. B.S. 5, 87



Be particular to state if a Report is also sent on the Hull of the Ship

* Certificate to be sent to the Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character of Ship and Machinery precisely as in the Register Book.

LON 680-0315

It is submitted that this vessel is eligible to have the notification B.S. 5.87 recorded, the boilers being subject to resurvey as per Rule.

D.P.
12/5/87

