

REPORT of SURVEY for REPAIRS, &c.

44545

Received in London Office, FRIDAY 26 AUGUST 1887

No. 44545

Port of *London*

No. in Reg. Book. Survey held at *London*

Date, First Survey *5th Aug* Last Survey *5th Aug 1887*
(No. of Visits)

279 on the *Iron Screw Steamer PICKWICK* Master _____ YEAR. MONTH.

TONNAGE:— Built at *Sunderland* By whom *W. Pile & Co.* When *1871*
NET *731* Owners *C. C. Barton* Port belonging to *M. Shuttle*
GROSS *1141*
UNDER DK. *899* Owner's Address _____
(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock afloat Name of Dock *Hillwell* Destined Voyage _____
Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. *44339* Port *London* Classed *S.S. 3-84 90 A1*
Character in Register Book. *10185*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in Winter ft. ins.
of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Condition*

This Vessel has been visited afloat in the Hillwell Dock, and a new stream anchor examined on board, with Certificate of test of which the following are particulars, viz—

*No. of Cert. 2898. South Dock, Sunderland 18th May 1876.
Dutch Palmed Anchor wt. 8.0.14. Proof Strain 10.5.0.0
Mark 18 75 RWCPT 2898 B&T J. Hartness, Super*

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (If Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulk'ng of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Fell.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c.:

The Vessel so far as seen appeared to be in a sound and efficient condition and eligible to remain as classed

	£	s	d	
Entry Fee (if chargeable) per Scale I., Sec. 27...				Fees received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27...				
Survey Fee (per Section 28)				
Special on Damage, Fee (if any) (per Sec. 28)....				
*Certificate (if required) to be sent as per margin				
Travelling Expenses (if chargeable)				
Second Surveyor's Fee (if any)				

Chas. H. Jordan
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____
Character assigned *90 A1*
5 Aug

TUESDAY 30 AUGUST 1887



Form No. 2 for Report—5000—11/87—Transcribe into—1887—The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

LON 681-0041