

REPORT of SURVEY for REPAIRS, &c.

48269

Received in London Office, 9 APRIL 1888

No. *746* Date of Writing Report *2/4/88* 188 *Port of London*
 No. in Reg. Book. *746* Survey held at *London* Date, First Survey *7/4/88* Last Survey *7/4/88*
 on the *"Smyrna"* Iron S. Master *Taylor*

TONNAGE:—
 NET *1305* Built at *Aberdeen* By whom *Flood* When *1876*
 GROSS *1372* Owners *G Thompson & Coy* Port belonging to *Aberdeen*
 UNDER DECK *1185* Owner's Address
 (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock *Dry Dock* Name of Dock *Greens* Destined Voyage *Sydney*
 Length of Poop *3* ft.: of Forecastle *3* ft.: of Raised Or. Deck *3* ft.: Moulded Depth *100A1*
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. *47284* Port *Lon* *Lon*
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
 Repairs, OR EXAMINATION AS PER RULE, FOR *Condition*
 Classified *100A1*
 in Summer *6-87* ft. ins.
 in Winter *100A1* ft. ins.
See Lon No 2-84.

This vessel was placed in dry dock, the bottom was examined cleaned & coated.

The marine Supt was advised of the impending Special Survey No 3 due this year.

PRESENT CONDITION OF THE							
<i>Good</i>		<i>Good</i>		<i>Good</i>		<i>Good</i>	
Decks		Plank (Bottom) & Counter		Ceiling		Boats	
Waterways		Treenails or Rivets		Rudder		Masts, Yards, &c.	
Comings		Breasthooks and Stemson		Windlass & Capstan		Condition, how ascertained	<i>from 2h</i>
Up'r Dk. Beams & Fastenings		Transoms, Pointers, & Crutches		Pumps		Sails	<i>Good</i>
Low'r Dk. Beams & Fastenings		Timbers of Frame at the opening		Cement (if Iron Ship)		Anchors	No. of <i>313, 15 2K</i>
Planksheers		Ditto ditto at other places		Caulking of Bot'm, D'k, & Watrways		Cables	<i>Good</i>
Sheerstrakes		Keelsons		Copper, or Y.M.		Hawsers & Warps	
Topsides		Clamps & Shelves		(State if on Felt.)		Standing & Running Rigging	
Wales				When put on		Hatches	
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.		Scuppers	<i>rod</i>	Cargo & Main Hatchways	<i>good</i>

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel now appears to be in a sound and efficient condition eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27... £
 Office Fee (if chargeable) per Scale II., Sec. 27... £
 Survey Fee (per Section 28) £
 Special on Damage, Fee (if any) (per Sec. 28).... £
 *Certificate (if required) to be sent as per margin £
 Travelling Expenses (if chargeable) £
 Second Surveyor's Fee (if any) £
 Committee's Minute *100A1*
 Character assigned *100A1*
 Fees applied for, 188
 Received by me, *Edward J. D. Turner*
 188
 Surveyor to Lloyd's Register of British & Foreign Shipping.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Smyna



© 2021

Lloyd's Register
Foundation