

REPORT of SURVEY for REPAIRS, &c.

48421X

Date of Writing Report Aug 21st 1888 Port of London Received in London Office WEDNES, 22 AUG 1888

Survey held at London Date, First Survey Aug 17th Last Survey Aug 17th 1888
 on the Fort Darwin (No. of Visits 1st) Master W. Morgan

AGE:—
1628 Built at Newcastle By whom A Leslie & Co When 1884
2517 Owners Anglo-Australian Str Mac Coy Port belonging to London
2423 Owner's Address
 (if not already recorded in Appendix of Register Book.)

Keel lashed Afloat or in Dry Dock Dry Dock Name of Dock St James Destined Voyage Newport & Mediterranean
 Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
 (if these particulars are not yet recorded in the Register Book.)

Survey, No. 368 Port Sydney Classed 100 A / Spar Deck
 by the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer _____ ft. _____ ins.
 on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in Winter _____ ft.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition of spar Deck not.
 This vessel was placed in dry dock the bottom examined in anticipation of S.P. not.
 See Secretary's letter dated Aug 20th/88 to owners.

CONDITION OF THE	Plank (Bottom) & Counter	Ceiling	Boats
<u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>
Treenails or Rivets	✓	Rudder	✓
Breasthooks and Stemson	✓	Windlass & Capstan	✓
Transoms, Pointers, & Crutches	✓	Pumps	✓
Timbers of Frame at the opening	✓	Cement (if Iron Ship)	✓
Ditto ditto at other places	✓	Caulking of Bot'm, D'k, & Watrways	✓
Keelsons	✓	Copper, or Y.M. (State if on Felt.)	✓
Clamps & Shelves	✓	When put on	✓
Coal Bunker, Openings, Lids, &c.	✓	Scuppers	<u>Good</u>
Beams & Fastenings	✓	Cargo & Main Hatchways	<u>Good</u>
Beams & Fastenings	✓	Hatches	✓
Skylights	✓	Masts, Yards, &c.	✓
Skylights	✓	Condition, how ascertained	<u>from deck</u>
Skylights	✓	Sails	<u>Good</u>
Skylights	✓	Anchors No. of	<u>3 B, 1 S, 2 K</u>
Skylights	✓	Cables	<u>Good</u>
Skylights	✓	Hawsers & Warps	✓
Skylights	✓	Standing & Running Rigging	✓
Skylights	✓	Standing & Running Rigging	✓
Skylights	✓	Hatches	✓

General Observations, Opinion as to Class, Recommendation, &c. :
 This vessel now appears to be in a sound and efficient condition eligible in my opinion to remain as classed. (S.P. not. to be held except examination in dry dock)

if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 20/8 1888
if chargeable) per Scale II., Sec. 28	£	:	:	
(per Section 28)	£	:	:	
Damage, Fee (if any) (per Sec. 28)	£	:	:	
(if required) to be sent as margin	£	:	:	Received by me, 14/9 1888
Expenses (if chargeable)	£	:	:	
Surveyor's Fee (if any)	£	:	:	

Thos H Gray
Edward Protheroe
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 31 AUGUST 1888 TUES 13 NOV 1888 FRIDAY 6 SEPT 1889
 Date assigned Deferred FRI 13 SEP 89 FRIDAY 20 DEC 1889
 LON683 - 2111