

# REPORT of SURVEY for REPAIRS, &c.

No.

Date of Writing Report

Jan 11 1889

1889

Port of London

Received in London Office,

12 JAN 1889

No. in Reg. Book.

Survey held at London

Date, First Survey Dec 17 1888 Last Survey Jan 10 1889

275 on the Tongariro

Steel Ship

Master Bone

TONNAGE:—

NET 2657

Built at Glasgow

By whom J. & C. Coy

When 1888

GROSS 4163

Owners New Zealand Ship Limited

Port belonging to Lyttelton

UNDER DEK 2755

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Royal Albert Destined Voyage New Zealand

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins. Character in Register Book.

Last Survey, No. 48779 Port London

Classed

100A1

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel was placed in dock, the bottom examined cleaned and coated, & several loose rivets in shell plating are renewed. Two watertight Hatches fitted on main deck at after end of main hold with shoots from them leading to Cross Bunker, one being fitted on each side in order to dispose of coal carried in the Tween Decks.

PRESENT CONDITION OF THE	Parts when run	Plank (Bottom) & Counter	Ceiling	Boats
Decks	Good	Good	Good	Good
Waterways	✓	Treehalls or Rivets	✓	Masts, Yards, &c.
Comings	✓	Breasthooks and Stemson	✓	Condition, how ascertained
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Sails
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the opening	✓	Anchors No. 20, 18, 20
Planksheers	✓	Ditto ditto at other places	✓	Cables
Sheerstrakes	✓	Keelsons	✓	Hawsers & Warps
Topsides	✓	Clamps & Shelves	✓	Standing & Running Rigging
Wales	✓		Copper, or Y.M. (State if on Felt.) When put on	Hatches
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	✓	
		Scupper	Good	Cargo & Main Hatchways

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	
Office Fee (if chargeable) per Scale II., Sec. 27...	£	
Survey Fee (per Section 28) .....	£	
Special on Damage, Fee (if any) (per Sec. 28) .....	£	
*Certificate (if required) to be sent as per margin	£	
Travelling Expenses (if chargeable) .....	£	
Second Surveyor's Fee (if any) .....	£	

Fees applied for,

188

Received by me,

188

Committee's Minute


Character assigned

JAN 15 1889

100A1 Spar Deck

Edward J. M. Surveyor

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation  
LON684-0460