

49237
REPORT of SURVEY for REPAIRS, &c.

No. 596 Date of Writing Report 188 Port of London
No. in Reg. Book. 596 Survey held at London Date, First Survey 25th Feb^y Last Survey 1st March 1889
(No. of Visits)

TONNAGE:—
NET 1653 Built at Middlesbro' By whom R. Dixon & Co When 1881 YEAR. MONTH. 3rd
GROSS 2542 Owners Bothwell Castle S.S. Owners (Lim.) T. Kemner & Co Port belonging to London

UNDER DEK. 2399 Owners' Address (if not already recorded in Appendix to Register Book.)
If Surveyed Afloat or in Dry Dock Afloat Name of Dock Victoria Docks Destined Voyage

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 49007 Port London Classed L.S. Lon. No 1-85 100A-1.
2.89

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
Society's Freeboard } in Summer ft. ins.
(if assigned) }
) as painted on Ship } in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Marking of freeboard.

The freeboard marks assigned for this vessel in 1883 have been repainted & verified on the port side. On the starboard side, the marks appear to be correct but could not be examined, as this side of the vessel was too near the quay.

PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Oppsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c.:

The freeboard marks on the starboard side should be verified on the vessel's return.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	0	0	
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	Received by me, 188
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute
Character assigned

Not for Council

L. H. Truscott.
Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

To be indexed
I put away.

20.7

6/11/89

Mr Bishop



© 2021

Lloyd's Register
Foundation