

49274
REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

THURS 14 MARCH 1889

No.

Date of Writing Report

12 March

1889

Port of

No. in
Reg. Book.

Survey held at

London

Date, First Survey

27 Feb

Last Survey

8 March

1889

on the

S.S. Long Ditton

Master

YEAR.

MONTH.

TONNAGE:-

NET

617

GROSS

812

UNDER DK.

727

Built at

Sunderland

By whom

J.R. Donald

When

1870

Owners

Commercial S.S. Co. (Ld)

Port belonging to

London

Owners' Address

(If not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Dry Dock

Name of Dock

Lincolns

Destined Voyage

Length of Poop

ft.

of Forecastle

ft.

of Raised Or. Deck

ft.

Moulded Depth

ft.

ins.

Years assigned,
if a Wood Ship.

Character in
Register Book.

Classed

Last Survey, No.

3575

Port

Off

Fifth Survey in 85

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

in Summer

ft.

ins.

in Winter

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition

This vessel has now been placed in dry dock cleaned and
overhauled. Portion of deck renewed, sundry repairs done to bulwarks
rails &c. Equipment overhauled. madder repaired.

The owner were informed that the sixth survey was due
but it has not been found convenient to go through this survey
now

PRESENT CONDITION OF THE

Decks	found	Hulk (Bottom) & Counter	found	Ceiling	found	Boats	Complete
Waterways	found	Tracings or Rivets	found	Rudder	found	Masts, Yards, &c.	found as seen
Comings	found	Breasthooks & Stemson	found	Windlass & Capstan	found	Condition, how ascertained	from deck
Up'r Dk. Beams & Fastenings	found	Transoms, Pointers, & Crutches	found	Pumps	found	Sails	found
Low'r Dk. Beams & Fastenings	found	Timbers of Frame at the openings	found	Cement (if Iron Ship)	found	Anchors	No. of 13 15 26
Planksheers	found	Ditto ditto at other places	found	Caulking of Bot'm, D'k, & Watrways	found	Cables	found as seen
Sheerstrakes	found	Keelsons	found	Copper, or Y.M.	found	Hawsers & Warps	found
Upsides	found	Clamps & Shelves	found	(State if on Plate)	found	Standing & Running Rigging	found
Wales	found		found	When put on	found	Hatches	found
Engine Room Skylights	found	Coal Bunker, Openings, Lids, &c.	found	Scuppers	found	Cargo & Main Hatchways	found

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel appears to be in good condition, & suitable, in my
opinion, to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	188
Survey Fee (per Section 28)	£	:	:	Received by me,
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	188
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute

FRIDAY 15 MARCH 1889

Character assigned

Deferred

to Owners 16/3/89

Per R. Cooper
Surveyor to Lloyd's Register of British & Foreign Shipping.

TUES. 7 APR 1891