

REPORT of SURVEY for REPAIRS, &c.

49802

Received in London Office, THURS 22 AUGUST

No. 188

Date of Writing Report

Port of

No. in Reg. Book.

Survey held at London

Date, First Survey 5th July Last Survey 21st Dec. 1889

40 on the Bk. "Kakaia"

Master

YEAR. MONTH.

TONNAGE:—

NET 1022

GROSS 1057

UNDER DEK. 893

Built at Sunderland By whom J. Blumer M^c When 1873

Owners New Zealand Sh. Co. (Lim)^d Port belonging to London

Owner's Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Afloat Name of Dock N. & Sh. Destined Voyage

Length of Deck ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No. 33 Port London

Classed

S.S. Lm. No. 3 - 9.86

100 A 1

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

On examination of this vessel the deck was found to be worn thin in places & in other parts defective.

This deck has now been cleared away & a new deck of yellow pine well laid & caulked. Fastenings galvanised iron bolts.

The post of the poop & the deck house, which were taken down for the purpose of laying the deck, have been refitted.

PRESENT CONDITION OF THE

Decks	new	found	Blank (Bottom) & Counter		Ceiling	placed	found	Boats	complete	found
Waterways	"	"	Trunnion or Rivets	pl. seen	Rudder	not seen		Masts, Yards, &c.	found	as seen
Comings	"	"	Breasthooks and Stemson	not seen	Windlass & Capstan	found		Condition, how ascertained	from deck	
Up'r Dk. Beams & Fastenings	"	"	Transoms, Pointers, & Crutches	"	Pumps	"		Sails	found	
Low'r Dk. Beams & Fastenings	"	"	Timbers of Frame at the opening	found	Cement (if Iron Ship)	not seen		Anchors	No. of 3/16. 18. 2h	
Planksheers			Ditto ditto at other places		Caulking of Bot'm, D'k, & Watrways	found		Cables	status to be complete	
Sheerstrakes	Rating	Lat. seen	Keelsons	placed	Scupperns on V.M.			Hawsers & Warps	found	
Topsides			Clamps & Shelves (Chimney)	"	(State when built)			Standing & Running Rigging	"	
Wales					When put on			Hatches	"	
Engine Room Skylights			Coal Bunker, Openings, Lids, &c.		Scupperns	found		Cargo & Main Hatchways	found	

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel appears to be in good condition, eligible, in my opinion, to remain as classed; with date of last survey 8.89. N.D. 89

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	2	2	9
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Fees applied for,

22/8 1889

Received by me,

24/10 1889

a J.P.

FRI 23 AUG 89

Committee's Minute

Character assigned

100 A 1

N.D. 89

Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register Foundation