

REPORT of SURVEY for REPAIRS, &c.

49951

Received in London Office.

THURS 24 OCT 1889

No. _____ Date of Writing Report _____ 18 _____ Port of _____
 Survey held at London Date, First Survey 27th Sept^r Last Survey 23rd Oct^r 1889
 on the S.S. Breconshire Master _____
 TONNAGE:— Built at Sunderland By whom Sunderland S.B. Co. When 1883 11
 NET 1648 Owners Jenkins H^r Port belonging to London
 GROSS 2544
 TONNAGE REGISTER DK. 2109 Owners' Address _____
 Surveyed Afloat or in Dry Dock Afloat Name of Dock Commercial Destined Voyage _____

Length of Poop _____ ft.: of Forecastle 38 ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
(if these particulars are not yet recorded in the Register Book.) Years assigned, if a Wood Ship. Character in Register Book.

Last Survey, No. 1677 Port Ant + P.M.C. 1289 Classed S.S. En. No 1-04 100 A 1
 2.89

State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer _____ ft. _____ ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.) as painted on Ship in Winter _____ ft. _____ ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Alteration

The forecastle of this vessel has been lengthened 8 feet an iron bulkhead being fitted at the after end. The original bulkhead being left in its place. This new arrangement necessitated the fitting of two new bulk beams + adding to the stringers + deck on the forecastle which has all been satisfactorily done.
 The vessel has not been put into dry dock

Sent to _____

NAME R

PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.) When put on	Hawsers & Warps
Topsides	Clamps & Shelves		Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :

My survey has only related to the above matter
 No alteration to be made in the date of survey

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 28.10.1889 Received by me, 17.2.1890
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	1	1	
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	29	190	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Geo. T. Cooper
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 1 NOV 1889
 Character assigned 100A1 as now

FRIDAY 22 NOV 1889

© 2021

Lloyd's Register Foundation

State if a Report is also sent on the Machinery or if not whether, and when, one will be sent.

Insert Character precisely as in Register Book.