

# REPORT of SURVEY for REPAIRS, &c.

No. *136* Date of Writing Report *18* Port of *London* Received in London Office, *TUES 31 DEC 1889*  
 No. in Survey held at *London* Date, First Survey *17 Dec* Last Survey *21 Dec* 18 *89*  
 Reg. Book. *on the S.S. Arena* (No. of Visits *Five*) Master *A. Jeyner*

TONNAGE:— NET *522* Built at *Sunderland* By whom *Darison & Co* When *1873* 9  
 GROSS *747* Owners *Paderi Akhi Port Arena* Port belonging to *Huddersfield*  
 UNDER DECK *548* Owner's Address *(if not already recorded in Appendix to Register Book.)*  
 If Surveyed Afloat or in Dry Dock *Afloat* Name of Dock *Commercial Dr* Destined Voyage  
 Length of Poop *ft.:* of Forecastle *ft.:* of Raised Or. Deck *ft.:* Moulded Depth *ft.* ins. *ins.*  
 (if these particulars are not yet recorded in the Register Book.) Years assigned, if a Wood Ship. Character in Register Book.

Last Survey, No. *49569* Port *London* *S.S. No. 1* Classed *90 A1*  
*S.S. No. 1 - 10.85* 6.89  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.) Society's Freeboard (if assigned) in Summer *ft.* ins. in Winter *ft.* ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *S.S. No. 1* *Marchy not complete*

This vessel has now been prepared for survey by the removal of ceiling in the holds & on the water ballast tank tops, in excess of the rule requirements. The holds, bunkers, again & brila space peaks & trim decks have been examined. The framework, riveting & surfaces of the iron plating were found to be in good condition & have been recently recrated. Some of the cement in the fore hold was away but this has now been made good. The water ballast tanks have been cleaned, painted, examined & tested in accordance with the rules & are in good condition. Ceiling has been relaid, such parts as were necessary being renewed. Mast spars & equipment generally have been overhauled, the chain cables being changed & found complete. The vessel was dry docked & examined by me on the 8<sup>th</sup> Dec last. See En. Report No 49569

PRESENT CONDITION OF THE							
Decks	<i>found</i>	Plank (Bottom) & Counter	<i>found</i>	Ceiling	<i>found</i>	Boats	<i>found</i>
Waterways	<i>found</i>	Stitching Rivets	<i>found</i>	Rudder	<i>found</i>	Masts, Yards, &c.	<i>found</i>
Comings	<i>found</i>	Breasthooks and Stemson	<i>found</i>	Windlass & Capstan	<i>found</i>	Condition, how ascertained	<i>inspected</i>
Up'r Dk. Beams & Fastenings	<i>found</i>	Transoms, Pointers, & Crutches	<i>found</i>	Pumps	<i>found</i>	Sails	<i>found</i>
Low'r Dk. Beams & Fastenings	<i>found</i>	Timber of Frame at the opening	<i>found</i>	Cement (if Iron Ship)	<i>found</i>	Anchors No. of	<i>3 B 15 24</i>
Sheerstrakes	<i>Plating found</i>	Plating at other places	<i>found</i>	Caulking of Bot'm, D'k, & Watrways	<i>found</i>	Cables	<i>found - complete</i>
Top-sides		Keelsons	<i>found</i>	Copper, or other plating	<i>found</i>	Hawsers & Warps	<i>found</i>
Wales	<i>found</i>	Clamps & Shelves	<i>found</i>	Wear-plates	<i>found</i>	Standing & Running Rigging	<i>found</i>
Engine Room Skylights	<i>found</i>	Coal Bunker, Openings, Lids, &c.	<i>found</i>	Scuppers	<i>found</i>	Cargo & Main Hatchways	<i>found</i>
Hatches	<i>found</i>						

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel is in good condition, suitable, in my opinion, to remain as classed & to be marked S.S. No. 1 - 89 with word of last survey 12.89.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,	
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:		
Survey Fee (per Section 28)	£	3	10	0	1890
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:		
Certificate (if required) to be sent as per margin	£	:	5	:	
Travelling Expenses (if chargeable)	£	:	10	:	0
Special Surveyor's Fee (if any)	£	:	:		

Committee's Minute *FRI 13 JAN 90*  
 Character assigned *Superior for complete of Marchy*  
 Received by me, *W. J. Cooper*  
 Surveyor to Lloyd's Register of British & Foreign Shipping.  
 FRIDAY 14 FEB 1890  
 90A1  
 Lloyd's Register Foundation  
 LON 1688 0124