

50702

REPORT of SURVEY for REPAIRS, &c.

Received in London Office, **MURS 29 MAY 1890**

No. 61 Date of Writing Report 18 Port of London
No. in Reg. Book 61 Survey held at London Date, First Survey 25 April Last Survey 24 May 1890
(No. of Visits 5)

on the S.S. Oceano Master _____
TONNAGE:—
NET 650 Built at Middlesex By whom Buckhouse & Dixon When 1871 8
GROSS 1004 Owners Catham & Co Port belonging to London
DK 934 Owner's Address _____

Surveyed Afloat or in Dry Dock Afloat Name of Dock Comm. Dock Destined Voyage _____
Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
(if these particulars are not yet recorded in the Register Book.)
L.M.C. 10.88 Classed _____
Years assigned, if a Wood Ship. _____
Character in Register Book. _____

Last Survey, No. 49977 Port London S.S. Im No 3 - 4.88 100A1
10.88
Cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer _____ ft. _____ ins.
on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter _____ ft. _____ ins.
Letters respecting this case. _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of repair
See Lon. Report No 49977 in which it is stated that "under a small house on the port awning deck the ends of this deck at the stowhead bulkhead were found defective"
This deck has now been renewed & part of the house itself. The trile hatchway cranning which was also found defective has now been repaired with new end.
vessel has not been placed in the dry dock

PRESENT CONDITION OF THE			
Waterways	Plank (Bottom) & Counter	Ceiling	Boats
Comings	Treenails or Rivets	Rudder	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Low'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Planksheers	Timbers of Frame at the opening	Cement (if Iron Ship)	Anchors No. of
Sheerstrakes	Ditto ditto at other places	Caulking of Bot'm, D'k, & Wat'rways	Cables
Upsides	Keelsons	Copper, or Y.M. (State if on Felt.) When put on	Hawsers & Warps
Wales	Clamps & Shelves		Standing & Running Rigging
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :

The above repairs have been done satisfactorily
No alteration to be made in the date of last survey

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	

Geo Morphey
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute **FRI 6 JUNE 1890**
Character assigned 100A1 on Lon Rep No: 49977

Insert Character precisely as in Register Book.