





50710 Lon

The masts. Spars and general equipment overhauled and the survey fully completed except that the bottom requires examination in dry dock which the owner propose to present for survey at Melbourne

The owner objected to drilling the outside plating and from a careful examination of the plating we are of opinion that drilling in this case is unnecessary.

The For upper topsail yard, For lower top Gallant yard. For lower top gallant yard, for royal yard, for top Gallant Mast, renewed.

Edward for Survey

J. Stanbury