

# Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

BAT 25 OCT 1890

No. \_\_\_\_\_ Date of Writing Report *Oct 24<sup>th</sup> 1890* Port of *London*  
 No. in Reg. Book. Survey held at *London* Date, first Survey *Oct 17<sup>th</sup>* Last Survey *Oct 17<sup>th</sup> 1890*  
 130 on the Machinery of the *A.S. Ferni Queen* Master *Barber* No. of Visits *1*  
 Tonnage } Gross *1208*  
 Net *914* Vessel built at *Hartlepool* By whom *Pile Spence & Co* When *1864 10*  
 Registered Horse Power } *104* Engines made at *Liverpool* When *1872* Boilers, when made (Main) *1882* (Donkey) *-*  
 No. of Main Boilers *1* Owners *W. H. Lomer* Port *London* Voyage \_\_\_\_\_  
 Steam Pressure in Main Boilers *45* If Surveyed Afloat or in Dry Dock *Princis*  
 in Donkey Boiler *1* (State name of Dock.) *dry dock* Class of Vessel & Machinery  
 (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) *A. 1. A. 1. 1. 6. 89*  
*B MS. 4. 88*  
*BS. 5. 90*

Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

## Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time?

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

*Sea connections & propeller partings seem satisfactory*

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1/89, B. & M.S. 1/89, or L.M.C. 1/89, as the case may be.)


*Eligible in my opinion to remain as classed*

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28) .....	£	:	:	18
Special Damage Fee (per Section 28) .....	£	:	:	} received by me,
*Certificate (if required) as per margin .....	£	:	:	
Travelling Expenses (if chargeable).....	£	:	:	18

*Francis Pickton*  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *TUES 28 OCT 1890*

Assigned *As now*



© 2019

Lloyd's Register Foundation

LON691-0138

State if a Report is submitted to the Ship or if not whether, and when, one will be sent.

Insert Character of Ship and Machinery precisely as in the Register Book

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this  
vessel is eligible to  
remain as  
classed.

MA.

27-10-90



© 2019

Lloyd's Register  
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN