

REPORT of SURVEY for REPAIRS, &c.

51717

No. 146 Date of Writing Report 18 Port of London Received in London Office, THURS. 26 MAR 1891
 No. in Reg. Book. 146 Survey held at London Date, First Survey 24th May Last Survey 24th March 1891
 (No. of Visits 1)

Master Wm. H. H. H. H. YEAR. 1889 MONTH. 10
 TONNAGE:— Built at Olsgow By whom R. Stephen Hms Port belonging to Olsgow
 NET 1157 Owners (Mackay & Co. Ltd.)
 GROSS 1784 Owners' Address (if not already recorded in appendix to Register Book.)
 UNDER DK. 1270

If Surveyed Afloat or in Dry Dock Afloat Name of Dock River Thames Destined Voyage

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 299 Port Bru + L.M.C. 10.89 Classed 100 A1 7.90

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter ft. ins.
 of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repair

See Antwerp Report No 1999 - 29th November 1890.
The repair to indented plating on the starboard side of this vessel has now been examined by me. It is an efficient repair, & nothing further is intended to be done until the vessel is docked for her annual overhaul, when it is intended to fair the indented parts

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulk'ng of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.) When put on	Hawsers & Warps
Topsides	Clamps & Shelves		Standing & Running Rigging
Wales			Hatches
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways

General Observations, Opinion as to Class, Recommendation, &c.:

In my opinion the matter is one that can be left for the owner's convenience as above noted.
No alteration to be made in date of last survey.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	18
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	Received by me,
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute FRL 3 APL 1891
 Character assigned Remain as classed
Rpro Note

Geo. T. Cooper
 Surveyor to Lloyd's Register of British & Foreign Shipping.

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent.

Form No. 2 for Repairs—1890—31/3/90.—Transfer Ink.—T. & S.J. The Surveyors are requested not to write on or below the space for Committee's Minute.