

REPORT of SURVEY for REPAIRS, &c.

No. 51876 Date of Writing Report May 6th 1891 18 Port of London Received in London Office, WED. 6 MAY 1891

No. in Reg. Book 596 on the Minnesota Steel S/S Date, First Survey Last Survey May 6th 1891

TONNAGE: NET 2009 GROSS 3079 UNDER DECK 2388

Built by Harland & Wolff at Belfast When 1887-11

Owners (Williamus Torrey Field) Port belonging to London

Owners' Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Silbury Destined Voyage Swansea

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth 11.50 ins.

(if these particulars are not yet recorded in the Register Book.)

Classed + L.L. C. 11, 87

Years assigned, if a Wood Ship. Character in Register Book.

Last Survey, No. 51026 Port London

Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.

Society's Freeboard (if assigned) in Summer 6 ft. 4 ins. in Winter - ft. - ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel was placed in dry dock, the bottom examined cleaned & coated. 12 rivets renewed in keel of Stern post. The vessel was reported to have been aground at Philadelphia

Notice was given to the marine Supt that this vessel was due for P. Enot. in Nov's next.

PRESENT CONDITION OF THE		Blank (Bottom) & Counter	Ceiling	Boats
Decks	Good	Good	Good	Good
Waterways	✓	Transoms or Rivets	Rudder	Masts, Yards, &c.
Comings	✓	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. 30, 32, 34
Planksheers	✓	Ditto ditto at other places	Caulking of Bot'm, Dk, & Wat'rways	Cables
Sheerstrakes	✓	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	✓	Clamps & Shelves	When put on	Standing & Running Rigging
Wales	✓			Hatches
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	Scuppers	
			Cargo & Main Hatchways	

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel now appears to be in a sound & efficient condition, eligible in my opinion to remain as classed with a fresh record of Survey Lon 5791

Entry Fee (if chargeable) per Scale I, Sec. 27...	£	:
Office Fee (if chargeable) per Scale II, Sec. 27...	£	:
Survey Fee (per Section 28)	£	:
Special on Damage, Fee (if any) (per Sec. 28)	£	:
*Certificate (if required) to be sent as per margin	£	:
Travelling Expenses (if chargeable)	£	:
Second Surveyor's Fee (if any)	£	:

Fees applied for,

Received by me,

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRI 15 MAY 1891

Character assigned 100A1

Shelter Dk with 17th



© 2019

Lloyd's Register Foundation

Lon 693-0047