

No. 52696

# REPORT of SURVEY for REPAIRS, &c.

SAT. 6 FEB 1892

Date of writing Report 5/2/92 When handed in at Local Office 5/2/92 Port of London

No. in Survey held at London Date, First Survey 15/1/92 Last Survey 5/2/92  
Reg. Book. 622 on the Gleione Don S. (No. of Visits) Master Sargent 84-90

TONNAGE:- Built at Glasgow By whom A Stephens & Co When 1876-9  
GROSS 1139 Owners Shaw Savill & Albion Co Port belonging to Southampton  
UNDER DK 984  
NET 1092 Owners' Address R T A Green Destined Voyage Nelson

Surveyed Afloat or in Dry Dock RTA Green Name of Dock  
WB=DBa tons; FPT tons; uE&B tons; CellDB tons; }  
APT tons; MT tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
CHARACTER. X for Special Survey. Date of last Survey and of Periodical Surveys. Year Assigned now or expired. Machinery and Boiler Surveys (including date of N.B., if any).  
Last Survey, No. 3585 Port Low Sal +100A1 2/91

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Where the replacement of Anchors or Chains is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)  
Society's Freeboard (if assigned) as painted on Ship and now verified 3 ft. 9 in.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

This vessel was placed in dry dock, the bottom examined, cleaned & rebated.

SUMMARY OF DAMAGE REPAIRS: — Plates, Faired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE		Transoms, Pointers, & Crutches		Copper, or Y.M. (State if on Felt.)		Hatches	
Docks	Good	Timbers of Frame at the openings	Good	When put on, Month	Year	Boats	Good
Waterways	✓	Ditto ditto at other places	✓	Rudder	good	Masts, Yards, &c.	from dk
Coamings	✓	Keelsons	✓	Windlass & Capstan	✓	Condition, how ascertained	good
Up'r Dk. Beams & Fastenings	✓	Clamps, Shells & Stringers	✓	Pumps	✓	Sails	3 B, 1 B, 2 R
Low'r Dk. Beams & Fastenings	✓	Skeling	✓	Engine Room Skylights	✓	Anchors No. of	stated complete
Plating	✓	Ceiling	✓	Coal Bunker, Open'gs, Lids, &c.	✓	Cables, length	not repaid
Planing	✓	Cement or Asphalt (State whether)	✓	Scuppers	✓	(State if not repaid)	sufficient
Treenails or Rivets	✓	Tanks (State if now tested.)	✓	Cargo & Main H'tch'ys	✓	Hawsers & Warps	good
Breastheads & Stemson	✓	Caulking of Bot'm, D'k, & Wat'r'ys	✓			Standing & Running Rigging	good

\* General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptnD91, &c."  
This vessel now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed with a fresh record of Survey Low 2/92

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for, : :  
Survey Fee (per Section 29) £ : : : 18. : :  
Special Damage or Repair Fee (if any) (per Sec. 25.) £ : : : : :  
Travelling Expenses (if chargeable) £ : : : : :  
Second Surveyor's Fee (if any) £ : : : : :  
Received by me, Edward J. Turner, Surveyor to Lloyd's Register of British & Foreign Shipping.

\* Is Certificate now required? Committee's Minute TUES. 9 FEB 1892 Character assigned 100A1



LON695-0198

Form No. 3 for Repairs. 205. L.R.P.H. 20,000-24991. -Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

N.B.—All alterations in the existing records should be underlined.