

REPORT of SURVEY for REPAIRS, &c.

SAT. 14 JAN 1893

Writing Report 14 Jan 93 When handed in at Local Office 18 is Port of London
 Survey held at London Date, First Survey 30 Dec 92 Last Survey 2 Jan 1893
 on the Wood, Iron or Steel Screw Steamer "Carib" (No. of Visits 3) Master
 TONNAGE: 437 Built at Stockton By whom Richardson, Duck & Co When 1882
 SS 1088 Owners Anderson, Anderson & Co Port belonging to Stockton
 ER DK. 912 Owners' Address
 (if not already recorded in Appendix to Register Book.)
 Surveyed Afloat or in Dry Dock? In Dry Dock Name of Dock West India Dry Dock. Destined Voyage

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 CHARACT. For Special Survey, Date of last Survey and of Periodical Surveys. Years Assigned and expired. Machinery and Boiler Surveys (including date of N.B., if any).
100 A. 1. 1,92 L.M.C. 1,91.
 S.S. Lon. No-2-91.
 Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Survey, No. 53249 Port London
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 CHARACT. For Special Survey, Date of last Survey and of Periodical Surveys. Years Assigned and expired. Machinery and Boiler Surveys (including date of N.B., if any).
100 A. 1. 1,92 L.M.C. 1,91.
 S.S. Lon. No-2-91.
 Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR repair of damage in connection with grounding.

This vessel has been placed in dry dock and the bottom examined. Found on the port side amidships in the third strake from keel plate, one plate indented, but not such as to affect the efficiency of the vessel. It is intended by the Marine Superintendent to have this plate refitted or repaired at an early opportunity. The cement in Nos 1, 2 & 3 ballast tanks examined and repaired in a few places. One boat renewed and one repaired.

OF DAMAGE REPAIRS: — Plates, Faired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

CONDITION OF THE		Hatches	
good	Transoms, Decks, & Crutches <u>not exam^d</u>	good	Boats <u>good</u>
good	Timbers of Frame at the openings <u>good</u>	good	Masts, Yards, &c. <u>good</u>
good	Ditto ditto at other places <u>good</u>	good	Condition, how ascertained <u>from deck</u>
good	Keelsons <u>not exam^d</u>	good	Sails <u>not exam^d</u>
good	Clamps, Struts & Stringers <u>good</u>	good	Equipment letter <u>not exam^d</u>
good	Sealing (State if examined) <u>good</u>	good	Anchors, No. of <u>not exam^d</u>
good	Ceiling <u>good</u>	good	Cables (state if now ranged) <u>no</u>
good	Cement or Asphalt (State which) <u>good</u>	good	length size
good	Tanks (State if now tested) <u>no</u>	good	Rule length size
good	Caulking of Bot'm, D'k, & Wat'rw'ys <u>good</u>	good	Hawsers & Warps <u>not exam^d</u>
good	Copper, or T.M. (State if on both) <u>good</u>	good	Standing & Running Rigging <u>good</u>
good	When put on, Month Year	good	
good	Rudder <u>good</u>	good	
good	Windlass & Capstan <u>good</u>	good	
good	Pumps <u>not exam^d</u>	good	
good	Engine Room Skylights <u>good</u>	good	
good	Coal Bunker, Open'gs, Lids, &c. <u>good</u>	good	
good	Scuppers <u>good</u>	good	
good	Cargo & Main H'tch'w'ys <u>good</u>	good	

Observations, Opinion as to Class, Recommendation, &c. —
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey;" "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."
 This vessel is in good and efficient condition, eligible in my opinion to remain as classed, and to have record of survey "1,93."

Fees applied for, 14/11 18 93
 Received by me, 16/11 18 93
 TUES. 17 JAN 1893
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 FRI 27 OCT 1893
 Lloyd's Register Foundation
 LON697-0551