

Report of Survey for Repairs, &c., of Engines and Boilers.

WED. 25 JAN 1893

(Received at London Office)

Date of writing Report. 25.1.93 18 When handed in at Local Office 18 Port of London

No. in Reg. Book. Survey held at London Date, First Survey 7 Last Survey Jan. 20 1893 (No. of Visits 1)

3 on the Machinery of the Wood, Iron or Steel S. S. F. F. Barry Master

Tonnage { Gross 867 Net 5745 Vessel built at Madras By whom Baillie & Dixon When 1872 - 8

Registered Horse Power 99 Engines made at Barcha When 1871 Boilers, when made (Main) 1881 (Donkey)

No. of Main Boilers Owners J. Owen & Co. Port London Voyage

Steam Pressure in Main Boilers 65 lbs. X Surveyed Afloat or in Dry Dock Union (State name of Dock.)

in Donkey Boiler

Last Survey No. Port

Particulars of Examination and Repairs (if any) London.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

| Particulars of Classification (which must be inserted <u>precisely</u> as in Register Book & Supplements). | | | |
|---|--|--------------------------------------|--|
| CHARACTER. ✕ for Special Survey. Date of last Survey and of Periodical Surveys. | | Years Assigned now expired. | Machinery and Boiler Surveys (including date of N.B., if any). |
| -1-100 A1 | | | L.M.C. 12.89 |
| 12.91 | | | B.S. 7.92. |
| S.S. Hapl. No 2-89 | | | |
| S.S. No 3-281 | | | |

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Vessel placed in dry dock. sea comms. examd. & found in good condn.
the propeller & its fastenings sound & the tail shaft a good fit in stern bush.

General Observations, Opinion, and Recommendation:— As far as seen this vessel
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9,92, B.&M.S. 9,92 or X.L.M.C. 9,92, as the case may be.)
appas. eligible to remain as classed.

| | | | | |
|--|---|---|---|------------------|
| Office or Registration Fee (per Sec. 27) | £ | : | : | Fees applied for |
| Survey Fee (per Section 28) | £ | ✓ | ✓ | |
| Special Damage Fee (per Section 28) | £ | : | : | Received by me, |
| Travelling Expenses (if chargeable) | £ | : | : | |

Geo. J. Wilkinson.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute FRI 27 JAN 1893

Assigned As now



© 2019

Lloyd's Register
Foundation

LON 698-0048

State if a Report is also now sent to the Committee or if not whether, and when, one will be sent.

*Certificate to be sent to the Committee

16—Lloyd's Form No. 3—Transfer Ink—5,000, 7,992.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

*It is submitted that
this vessel is eligible to
remain AS CLASSED.*

W.A.

26-1-93

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation