

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUES. 10 JAN 1893

Date of writing Report Jan 9 18 93. When handed in at Local Office London is Port of London.

No. in Reg. Book 700 Survey held at London Date, First Survey Jan 7 Last Survey Jan 7 1893

on the Machinery of the Wood, Iron or Steel S.S. BUNGAREE Master Goodham

Tonnage { Gross 2893 Net 1859 Vessel built at Newcastle By whom W. Richardson & Co. When 1889 9. YEAR. MONTH.

Registered Horse Power 450 Engines made at Do. When 1889 Boilers, when made (Main) 1889 (Donkey) 1889

No. of Main Boilers Two Owners W. Lund Port London Voyage Australia

Steam Pressure in Main Boilers 160 lbs If Surveyed Afloat or in Dry Dock Brown's Dry Dock Refar.

in Donkey Boiler 80 lbs (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port

Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assessed and expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100. A.1.</u> <u>7.92.</u>		<u>L.M.C.</u> <u>9.89.</u>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

No.
No.
Survey not due

Completed.
Examined propeller, stem bush & sea connections fastenings, all
found to be in good condition.

General Observations, Opinion, and Recommendation:—This vessel's machinery is now
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey:
Thus, for example, B.S. 0,02, B.&M.S. 0,02 or L.M.C. 0,02, as the case may be.)
as far as seen in good condition & in my opinion the vessel is eligible
to remain as classed without fresh record of survey.

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	Received by me,
Travelling Expenses (if chargeable).....	£	:	:	18

P. M. Salmon.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute TUES. 31 JAN 1893

Assigned As now

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

*Certificate to be sent to.

16-LRPH—Form No. 9—Transfer Ink—5,000, 7/9/92.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

CWS.

27.1.93

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019
Lloyd's Register
Foundation