

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 1/5/93 18... When handed in at Local Office 1/5/93 18... Port of London
No. in Reg. Book. Survey held at London Date, First Survey 28/4/93 Last Survey April 29, 1893
(No. of Visits)

No. in Reg. Book. *376* Survey held at *London* Date, First Survey *28/4/93* Last Survey *April 29 '18 93*
on the *Wool, Iron or Steel* *S/S "Plover"* (No. of Vessels) Master *Fisher*

TONNAGE:—
GROSS 908
Built at Sunderland By whom Mounsey & Porter
When 1875-4
Owners General Steam Nav Co
Port belonging to Port of London

UNDER DEK. 792
NET 561
Owners' Address
(If not already recorded in Appendix to Register Book.)
Sumner Afloat in the Deck of the Vessel
Name of Deck

Surveyed Afloat or in Dry Dock *at* Name of Dock *East India Pier* Destined Voyage *Continental*

WB=DBa *tons*; *165* tons; uE&B *tons*; CellDB *tons*;

FPT *tons*; APT *tons*; MT *tons*;

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

Last Survey, No. 54085 Port Haven

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes, and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

CHARACTER.	Year Assigned.	now expired.
* for Special Survey. Date of last Survey and of Previous Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).	
+ 100A.1. 3/9/	+ N B 11/88 Cmc 11/88 1/89	
P.S. Dm No 3. 11/88		
Society's Freeboard (if assigned) as printed on Ship and now verified	2 ft. 10 ins.	

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Condition*

This vessel was seen lying afloat in East Lane
Bier in the River Thames. The new length of
chain cable supplied to the port side was
ranged out for inspection (15 fathoms) and the
no of the certificate appears to be 20485 not 20483
as reported. The marks are 7-90 LPH-N. 20485

The owners have been advised & recommended to produce a certificate in the ordinary course

Σ. 97

SUMMARY OF DAMAGE REPAIRS :—.....Plates, Faired or Repaired ;.....Frames, ditto.Plates, Renewed ;.....Frames, ditto. Other Repairs.

[illegible]

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel now appears to be in a sound & efficient condition, eligible in my opinion to remain as classed and to have a fresh record of Survey Log 4793 & to have the notation for the S. S. No. 1 recorded upon the

Office Fee (if chargeable) <i>per Section II., Sec. 27</i>	£	:	:	Fees applied for	production of the certificate of
Survey Fee (<i>per Section 28</i>)	£	:	:	18.	test of the cable above alluded to
Special Damage or Repair Fee (if any) (<i>per Sec. 28.</i>)	£	:	:	Received by me,	Edward Protheroe
Travelling Expenses (if chargeable)	£	:	:	18.	Surveyor to Lloyd's Register of British & Foreign Shipping.
Second Surveyor's Fee (if any)	£	:	:		

*Is Certificate now required?

TUES. 9 MAY 1893

Committee's Minute

Character assigned

es. No. 1-93

© 2019

Lloyd's Register
Foundation

LON 698- 0497