

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 11/8/93 When handed in at Local Office 11/8/93 Port of London
No. in Survey held at London Date, First Survey T Last Survey 10 May 1893
Reg. Book. 1182 on the Wood, Iron or Steel S. S. "Cruzco." (No. of Visits) Master Anderson 89-90
YEAR MONTH

TONNAGE:- Built at Glasgow By whom G. Elder & Co When 1871-10
GROSS 3898 Owners Orient Steam Navigation Co Port belonging Liverpool
UNDER DECK 3814 Owners' Address
NET 2506 (if not already recorded in Appendix to Register Book.)
Surveyed Afloat or in Dry Dock Dry Dock Name of Dock L.A. Dock Destined Voyage Australia

W.B.=DBa tons; f tons; uE&B tons; CellDB tons; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
FPT tons; APT tons; MT tons.

X.B.—All alterations in the existing records should be underlined.

Last Survey, No. 54825 Port Lon 7.8 Running Dock 4/93 N.E. 13/188 L.L.C. 12/92
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes and besides being detailed in the body of the report, should be summarised in the form shown below. Where the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)
Survey Lon 7/90 12 5 1/2 ins.
Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

This steamer was placed in dry dock, the bottom examined cleaned & coated.

SUMMARY OF DAMAGE REPAIRS:—Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE		Good		Good		Good	
Decks		Good		Transoms, Porters, & Gunboats	Good	Copper, on V.M.	Good
Waterways		✓		Timbers of Frame at the openings	✓	(State if renewed)	
Coamings		✓		Ditto ditto at other places	✓	When put on, Month	Year
Up'r Dk. Beams & Fastenings		✓		Keelsons	✓	Rudder	Good
Low'r Dk. Beams & Fastenings		✓		Clamps, Shells & Stringers	✓	Windlass & Capstan	✓
Plating		✓		Siding	✓	Pumps	✓
Planking		✓		(State if renewed.)	✓	Engine Room Skylights	✓
Transoms		✓		Ceiling	✓	Coal Bunker, Open'gs, Lids, &c.	✓
Rivets		✓		Cement or Asphalt	✓	Scuppers	✓
Breasthooks & Stanchions		✓		(State if renewed.)	✓	Cargo & Main Hatchways	✓
				Tanks	✓		
				(State if now tested.)	✓		
				Caulking of Bot'm, D'k, & Wat'r'ys	✓		

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 991," or "to remain as classed and to have record of survey, 991, and the notations of ss No. 1-91 and ptND91, &c."

This steamer now appears to be in a sound & efficient condition, eligible in my opinion to remain as classed with a fresh record of Survey Lon 8/93.

Office Fee (if chargeable) per Scale II, Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 28.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

*Is Certificate now required?

Committee's Minute

Character assigned ✓

Fees applied for,

18

Received by me

18

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

LON649-0408

FRI 18 AUG 1893

A 1. 1

7.8. + Among sk

Is a Report also sent now on the Machinery of the Ship? If not, state whether, and when, one will be sent?

* Certificate, if required, to be sent to

Form No. 2 for Repairs, 265.—L.R.P.H.—10,000.—8/2/93.—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)