

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 28(8)93 When handed in at Local Office 28(8)93 Port of London

No. in Reg. Book. Survey held at London Date, First Survey Aug 12/93 Last Survey Aug 25th 1893
186 on the Wood, Iron or Steel S.S Newburn (No. of Visits) Master Tom Lain 80 - 80
TONNAGE: Built at Sunderland By whom I Lain
GROSS 680
UNDER D.K. 624
NET 422
Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Lunebuu DK Destined Voyage Shields
WB=DA 130 tons; F.P.T. tons; U.E&B tons; Cell DB tons; MT tons.
F.P.T. tons; A.P.T. tons; M.T. tons.
N.B.—All alterations in the existing records should be underlined.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
CHARACTER.	
<input checked="" type="checkbox"/> for Special Survey.	Date of last Survey and of Periodical Surveys.
Length now exp'd.	Machinery and Boiler Surveys (including date of N.B., if any).

Last Survey, No. 53829 Port Lon

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs,
in consequence of taking the ground abreast of
the Beacon on the Black Middens, on 7th Aug/93
while on a voyage from Shields to Grimsby.

This steamer was placed in dry dock, the bottom examined & subsequently cleaned & coated on the port side:— In P strake 3 plates renewed.
in G strake 2 plates renewed, fairing up place in D strake 2 plates renewed, in E one fairing in place, in F 2 renewed
on the Starboard Side:— In B strake 3 renewed in G 1 renewed, in D 2 renewed.
The cement repaired where necessary replaced.

SUMMARY OF DAMAGE REPAIRS:— Plates, Fairied or Repaired; Frames, ditto. 14 Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE Decks	
Good	Transoms, Pointers, & Crutches
Waterways	Timbers of Frame at the openings
Coamings	ditto at other places
Up'r Dk. Beams & Fastenings	Keelsons
Low'r Dk. Beams & Fastenings	Clamps, Shelfs, & Stringers
Plating	Safing (State if now renewed.)
Planking	Ceiling
Bulkheads	Cement & Asphalte (State if now renewed.)
Timbers or Rivets	Tanks (State if now tested.)
Breasthooks & Stanchions	Caulking of Bot'm, Dk', & Wat'rwy's

Good	
Timbers of Frame at the openings	Copper, or Y.M. (State if on Felt.)
ditto at other places	When put on, Month
Keelsons	Rudder
Clamps, Shelfs, & Stringers	Windlass & Capstan
Safing (State if now renewed.)	Pumps
Ceiling	Engine Room Skylights
Cement & Asphalte (State if now renewed.)	Coal Bunker, Open'gs, Lids, &c.
Tanks (State if now tested.)	Scuppers
Caulking of Bot'm, Dk', & Wat'rwy's	Cargo & Main H'tch'w'y's

Good	
Hatches	Boats
Boats	Masts, Yards, &c.
Masts, Yards, &c.	Condition, how ascertained
Condition, how ascertained	Sails
Sails	Equipment letter
Equipment letter	Anchors, No. of
Anchors, No. of	Cables (State if now ranged)
Cables (State if now ranged)	length Rule length size
length Rule length size	comple
comple	size
size	length Rule length size
length Rule length size	Hawsers & Warps
Hawsers & Warps	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9/91," or "to remain as classed and to have record of survey, 9/91, and the notations of ss No. 1-91 and ptnd91, &c."

This steamer now appears to be in a sound and efficient condition eligible in my opinion to remain as classed with a fresh record of Survey Lon 8/93

Office Fee (if chargeable) per Scale II., Sec. 27	£	:	Fees applied for,
Survey Fee (per Section 28)	£	:	31/8 1893
Special Damage or Repair Fee (if any) (per Sec. 28)	£	:	Received by me,
Travelling Expenses (if chargeable)	£	:	11/9 1893
Second Surveyor's Fee (if any)	£	:	

*Is Certificate now required?

Committee's Minute

Character assigned

TUES. 29 AUG 1893

Edward J. Ferrey
Surveyor to Lloyd's Register of British & Foreign Shipping.

© 2019



Lloyd's Register
Foundation

LONG 699-0468

54669 Lon.

where disturbed.
The Ballast Tank tested with water to
a ascertain its efficiency sufficient
ceiling being removed for this purpose.
The cement granning examined all
for and aft

Edward J. Tierney.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation