

Date of writing Report 5th Sep 93 When handed in at Local Office 5th Sep 93 Port of London

No. in Reg. Book. 1 Survey held at London Date, First Survey Aug 21st 93 Last Survey Sept 5th 1893

(No. of Years) 1

581 on the ~~Wood, Iron or Steel~~ *S/S Alyera* *nine* Master *M. Moya* 92-92
YEAR MONTH.

TONNAGE:- 3282 Built at Volosat By whom Starland Hoof When 1888-5
GROSS 3282 Net 2400 Part belonging to Starland Hoof

UNDER NO. 2984 Owners' Address 1001 E. Main St., Port Belonging to ...

NET 2117 (if not already recorded in Appendix to Register Book.)
 Surveyed Afloat or in Dry Dock ✓ Name of Dock Brown Tally Destined Voyage Manitoul

WB=DBa _____ tons; f _____ tons; uE&B _____ tons; CellDB 545 tons; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

Last Survey No. 214 Port *Quinn* + 100 A.1. *Dec 12/92*

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs

on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles replaced, together with the weight of the new articles, should be given.

should be clearly stated, and also the weight, size, &c., required of the plates, together with the necessary equipment and Letter, if any. State also the dates and initials of any letters respecting this subject.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage, repairs
in collision with a tugboat caused by a collision with

the 38 Blue Star of Bendon on the 5th June 1832. Bunker

the / Continuation of Journal in the camp near Quana

This steamer was placed in dry dock, the bottom

examined, cleaned & coated, the rudder & tail

and pinos bushed.

The stem failed in place. 2 plants, one each side of

Specimen removed in the 2nd snake below sheer so permit
 it to slip all the way down the 1st snake.

of this also all the rivers above the 18 feet mark & then
subsequently to the 2000

Signature replaced.

8-

SUMMARY OF DAMAGE REPAIRS: — 2 Plates, Faired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Rep. Slam fairs in place

Decks	Transoms, Pointers, & Crutches	Copper on V M	Hatches
Good	Good	Good	Good

Waterways	✓	Timbers of Frame at the openings	✓	When put on Month	✓	Boats	✓
Joamings	✓	Ditto ditto at other places	✓	Rudder	✓	Masts, Yards, &c.	✓

Up'r Dk. Beams & Fastenings	✓	Keelsons	✓	Windlass & Capstan	✓	Condition, how ascertained	from Wt
		Chains, Sh. & Stays	✓			Sails	found

4 1/2" x 6" x 1/2" Dk. Beams & Fastenings..... 4
 4 1/2" x 6" x 1/2" Salting..... 4
 4 1/2" x 6" x 1/2" (See also numbered.)..... 4
 4 1/2" x 6" x 1/2" Pumps..... 4
 4 1/2" x 6" x 1/2" Engine Room, Skylights..... 4
 4 1/2" x 6" x 1/2" Equipment letter..... 4
 4 1/2" x 6" x 1/2" Anchors, No. of 3 B, 1 S, 2 R

Engine Room Skylights.....	✓	Cables (State if now ranged).....	no
Coal Bunker, Open'gs, Lids, &c.....	✓	" length.....	size.....

Rivets.....
 Tanks.....
 (State if now tested.)
 Scuppers.....
 " Line length..... size.....
 Hawser & Warps.....

General Observations. Opinion as to Class Recommendation &c. —

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“.....to remain as now classed in the Register Book *without fresh record of Survey*,” “to remain as classed and to have record of *Survey*,” &c., &c.

This steamer now appears to be in a Grand Old Ship

condition enable in the opinion to remain so

closed with a fresh record of Survey Box 9/93

1871

License Fee (if chargeable) per Section 27 £ : : Fees applied for, 2/9/83
 Survey Fee per Section 28 £ : : 18.00

Special Damage or Repair Fee (if any) \$2.25 : Received by me, Edward J. Foy

Travelling Expenses (if chargeable) £ 4/9 18/3

Second Surveyor's Fee (if any) 0

Surveyor to Lloyd's Register of British & Foreign Shipping.

Is Certificate now required?

Committee's Minute

Character assigned FOUR

LDN699-0502
