

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *Decr 30th 93* When handed in at Local Office *18* Port of *London*
No. in Reg. Book *353* Survey held at *London* Date, First Survey *Decr 21st 93* Last Survey *Decr 28th 1893*
on the *Wool, Iron or Steel* *Sc. Sn. "Lisbon"* Master *J. E. Holl.*
TONNAGE:— Built at *W. Hartlepool* By whom *Denton Gray & Co* When *1871-7*
GROSS *1334* Owners *J. Hall Jr. & Co* Port belonging to *London*
UNDER DK. *1294* Owners Address
NET *860* (if not already recorded in Appendix to Register Book.)
Surveyed Afloat or in Dry Dock? *Afloat* Name of Dock *London St.* Destined Voyage *Lisbon*

WB=DBa tons; f tons; uE&B tons; CellDB tons; } Particulars of Classification (which must be inserted
FPT tons; APT tons; MT tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
Last Survey, No. *54580* Port *London*
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Year Assigned now required. Machinery and Boiler Surveys (including date of N.B., if any).
* 100. A. 1. * N. B. 10. 90.
S.S. Lon. N. 3, 11. 82. I. M. C. 10. 90.
S.S. Hpl. N. 2. 90.
7. 93
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Repairs of Damage.*
The following temporary repairs of damage caused by stress of weather, have now been done. Viz—
On Starb. side, 20ft of top gallant bulwark (aft of bridge) repaired, 20ft of Main rail temporarily repaired, 2 bulwark plates doubled on the inside, 4 bulwark staunchions straightened and re-riveted, 4 chain plates slightly started, re-riveted as required, 1 bulwark port door repaired and two new hinges fitted, 2 sheer strake plates slightly cracked, (above the gunwale angle.) The deck abreast of Engine room skylight recaulked, 30ft Main rail and top gallant bulwark, abreast of fore rigging temporarily repaired.

SUMMARY OF DAMAGE REPAIRS:— 2 Plates, Faired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs *As above*

PRESENT CONDITION OF THE			
Decks	Transoms, Pointers, & Crutches	Copper, or Y.M. (State if on felt.) When put on, Month Year	Hatches <i>Good</i>
Waterways	Timbers of Frame at the openings	Rudder	Boats
Coamings	Ditto ditto at other places	Windlass & Capstan <i>Good</i>	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Pumps	Condition, how ascertained <i>From SR</i>
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	Engine Room Skylights	Sails <i>Stated Good</i>
Plating	Salting (State if examined.) Ceiling	Coal Bunker, Open'gs, Lids, &c.	Equipment letter
Planking	Cement or Asphalt (State which.) Tanks (State if now tested.) Caulking of Bot'm, D'k, & Wat'rw'ys	Scuppers	Anchors, No. of <i>3 B. 18. 2 H.</i>
Treenails or Rivets		Cargo & Main H'tch'w'ys	Cables (State if now ranged) <i>No</i>
Breasthooks & Stemson			" length <i>Stated complete</i>
			" Rule length <i>size</i>
			Hawsers & Warps <i>Good</i>
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."
As the damage does not affect the safety of the vessel, I am of opinion that with the above mentioned temporary repairs, she can proceed on her voyage, and effect permanent repairs at the Owners convenience.

Office Fee (if chargeable) per Scale II, Sec. 27 £ : : Fees applied for, 18.
Survey Fee (per Section 28) £ : : Received by me, *P. T. Johnson.*
Special Damage or Repair Fee (if any) (per Sec. 28.) £ : : 18.
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :
*Is Certificate now required? _____

Committee's Minute *Deferred for*
Character assigned *Write Own permanent*
16.1.94 repairs
TUES. 21 AUG 1894
Lloyd's Register Foundation
LON701-0016