

Report of Survey for Repairs, &c., of Engines and Boilers.

25 APR. 94

(Received at London Office)

Date of writing Report *April 24* is *94* When handed in at Local Office *London* is *Port of London*

No. in Reg. Book. *25* Survey held at *London* Date, First Survey *and* Last Survey *April 24, 1894*

on the Machinery of the Wood, Iron or Steel *S.S. "M. GAREL"* Master *Pary.*

Tonnage { Gross *1431* Net *926* Vessel built at *H. Shields* By whom *J & W. Smith* When *1883* 11.

Registered Horse Power *160* Engines made at *Newcastle* When *1883* Boilers, when made (Main) *1883* (Donkey) *1883*

No. of Main Boilers *2* Owners *(Scrutton Bros & Co)* Port *London* Voyage *W. Indies*

Steam Pressure in Main Boilers *80 lbs* If Surveyed *Afloat* in Dry Dock *S.W. India Dry Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boiler ☒

Last Survey No. *Port* Particulars of Examination and Repairs (if any) *Condition*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER. X for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned how expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<i>100 A.1.</i>	<i>10.93.</i>	<i>L.M.C.</i>
<i>SS. LON. 1003. 6.92</i>		<i>B.S. 7.93</i>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No.*

Do, " Donkey " " " " *No.*

If this was not done, state for what reasons? *Survey not due.*

And what parts of the Boilers could not be thus thoroughly examined? *No.*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *No.*

Did the Surveyor examine the Safety Valves of the Main Boiler? *No.*

At what pressure were they afterwards adjusted under steam? *No.*

Did the Surveyor examine the Safety Valves of Donkey Boiler? *No.*

To what pressure were they afterwards adjusted? *Completed.*

If the Survey is not complete state what arrangements have been made for its completion?


Examined propeller, Stern bush, & Sea connections fastenings, Tail end shaft drawn in & examined, all found to be in good condition.

General Observations, Opinion, and Recommendation:—*This vessel's Machinery is now as far as seen in good condition & in my opinion the vessel is eligible to remain as classed without fresh record of Survey.*

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	18
Special Damage Fee (per Section 28)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18

E. M. Salmon.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required
Committee's Minute *TUES. 1 MAY 1894*
Assigned *as now*



State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

14-LRPH—Form No. 9—Lloyd's Register Ltd.—4,000,210/93.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

A. R. F.

28-4-94

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN



© 2019

Lloyd's Register
Foundation