

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 3<sup>rd</sup> May 1894 When handed in at Local Office

Port of London

No. in  
Reg. Book.

Survey held at London

Date, First Survey 25<sup>th</sup> April Last Survey 2<sup>nd</sup> May 1894

141

on the Wood, Iron or Steel

S.S. "Howarden Castle"

Master

May

YEAR. MONTH.

TONNAGE:-

Built at Glasgow

By whom J. Elder &amp; Co.

When 1883.

1

GROSS 4380

UNDER DK. 4012

NET 2556

Owners D. Currie &amp; Co.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port belonging to London

Surveyed Afloat or in Dry Dock? D. Ok Name of Dock James J. Morris Destined Voyage Cape Town

WB=DBa ✓ tons; f ✓ tons; uE&B ✓ tons; CellDB ✓ tons; }  
FPT ✓ tons; APT ✓ tons; MT ✓ tons.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

Last Survey, No. 54904 Port Low

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of Periodical Survey.  
Years Assigned  
Machinery and Boiler  
Surveys  
(including date of N.B., if any).

100 A.1 + 11.91 + 2 M.E. 7.91  
S.S. 26 11.91 + 2 M.E. 7.91

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Keel and bottom examined  
in dry dock, and the bottom cleaned and recoated.

SUMMARY OF DAMAGE REPAIRS: - ✓ Plates, Paired or Repaired; ✓ Frames, ditto. ✓ Plates, Renewed; ✓ Frames, ditto. Other Repairs. ✓

PRESENT CONDITION OF THE

Decks	Transoms, Pointers, & Crutches	Copper, or I.M.	Hatches
Waterways	Timbers of Frame at the openings	(State if on Roll.)	Boats
Coamings	Ditto ditto at other places	When put on, Month	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Rudder	Condition, how ascertained
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	Windlass & Capstan	Sails
Plating	Soleing (State if examined.)	Pumps	Equipment letter
Planking	Ceiling	Engine Room Skylights	Anchors, No. of
Wearers or Rivets	Cement or Asphalt (State which.)	Coal Bunker, Open'gs, Lids, &c.	Cables (State if now ranged)
Breasthooks & Stemson	Tanks (State if now tested.)	Scuppers	length size
	Caulking of Bot'm, D'k, & Wat'rwys	Cargo & Main H'tch'wys	Rule length size
			Hawsers & Warps
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &amp;c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and PENDING, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed, with record 5.94.

Office Fee (if chargeable) per Sec. 11, Sec. 2	£	Fees applied for,
Survey Fee (per Section 25)	£	18
Special Damage or Repair Fee (if any) (per Sec. 25.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

\*Is Certificate now required?

Committee's Minute

Character assigned

TUES. 8 MAY 1894

100A1



© 2019

Lloyd's Register  
Foundation

LON702-0061