

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 27th Oct 1894 When handed in at Local Office 18 Port of London

No. in Survey held at London Date, First Survey 23rd Oct Last Survey 24th Oct 1894
Reg. Book. 893 on the Wood, Iron or Steel 13th Kaurunui Master

TONNAGE: - Built at Newcastle By whom Palmer C^o When 1875. 9
GROSS 1053 Owners New Zealand Shipping C^o Ltd Port belonging to London

UNDEK DK. 885 Owners' Address East India Destined Voyage

NET 1012 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? 9. 9 Name of Dock East India Destined Voyage

WB=DBa - tons; f - tons; uE&B - tons; CellDB - tons; FPT - tons; APT - tons; MT - tons.

F.B. - All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 54963 Port London

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Hull and bottom examined in dry dock. The hull repaired and the bottom cleaned and repainted.

CHARACTER OF DAMAGE REPAIRS: - Plates, Paired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

BEST CONDITION OF THE		Worst		Copper or Tin (When put on, Month)		Hatches	
Transoms, Pointers, & Crutches	9	9	9	Boats	9	9	9
Members of Frame at the openings	9	9	9	Masts, Yards, &c.	9	9	9
Water ditto at other places	9	9	9	Condition, how ascertained	9	9	9
Keelsons	9	9	9	Sails	9	9	9
Clamps, Shells & Stringers	9	9	9	Equipment letter	9	9	9
Siding (State if examined.)	9	9	9	Anchors, No. of	9	9	9
Ceiling	9	9	9	Cables (state if now ranged)	9	9	9
Cement or Asphalt (State which.)	9	9	9	" length	9	9	9
Keels (State if now tested.)	9	9	9	" Rule length	9	9	9
Caulking of Bot'm, D'E, & Wat'rw'ys	9	9	9	Hawsers & Warps	9	9	9
				Standing & Running Rigging	9	9	9

Opinion as to Class, Recommendation, &c.:-

That alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon to remain as now classed in the Register Book without fresh record of Survey, "to remain as classed and to have record of record of survey, 9,91, and the notations of ss No. 1-91 and pND91, &c."

This vessel is now in good and sound condition, and eligible to remain as Classed.

Fees applied for, 18
Received by me, W. M. Overly
18
Surveyor to Lloyd's Register of British & Foreign Shipping.



If a Report also sent now on the Machinery of the Ship, if not, state whether, and when, one will be sent?