

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report	31-10-94	When handed in at Local Office	31-10-94	Port of London
No. in Reg. Book.	Survey held at	London	Date, First Survey	Last Survey
1016	on the Wood, Iron & Steel	88. <u>Straight Fisher</u>	(No. of Visits)	89-10-94
TONNAGE:-	Built at	Belfast	Master	3 Woods 92
GROSS 465	Owners	J. Fisher & Sons	YEAR.	YEAR.
UNDER D.K. 376	Owners' Address	Port belonging to Barrow		
NET 185	if not already recorded in Appendix to Register Book			
Surveyed Afloat or in Dry Dock?		Afloat	Name of Dock	Destined Voyage
WB= DBa	tons; f	17 tons; u E&B	36 feet	Boulogne
F.P.T.	12 tons; A.P.T.	32 tons; M.T.	tons;	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 55922 Port London

(Periodical Surveys, when held, must be reported in detail and serial in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Part 8-8-Mo 1

This vessel was seen lying afloat in the River Thames at Chamberlain's Wharf Bermondsey.

The ballast tank forward was refitted to ascertain the efficiency of the bulkhead which was hidden by cargo on the last occasion.

The ballast tank under Boilers was tested with water as required by the Rules.

To complete the survey, the close lining on the sides of the holds required to be removed for examination of plating & framing. The peak ballast tanks examined inside.

SUMMARY OF DAMAGE REPAIRS :— Plates, Fair'd or Repaired ; Frames, ditto. Plates, Renewed ; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE	Decks	Good	Transoms, Pointers, & Guttering	Good	Copper, or Y.M. (State if on Bolt.)	Hatches	Good
Watertight	•		Timbers of Frame at the openings	•	When put on, Month		
Comings	•		Ridge ditto at other places	•	Rudder	Good	
Up'r Dk. Beams & Fastenings	•		Keelsons	•	Windlass & Capstan	*	
Lower Dk. Beams & Fastenings	•		Clamps, Sheats, Stringers	•	Pumps	*	
Mating	•		Salting (State if examined.)	•	Engine Room Skylights	*	
Blanking	•		Ceiling	•	Coal Bunker, Open'gs, Lids, &c.	*	
Scourer Rivets	•		Cement on Asphalt (State if examined.)	•	Scuppers	*	
Breasthooks & Scourers	•		Tanks <u>400</u> (State if now tested.)	•	Gage & Main H'tch'w'y's	*	

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9.91," or "to remain as classed and to have record of survey, 9.91, and the notations of ss No. 1-91 and PTND91, &c."

This steamer now appears to be in a sound & efficient condition, eligible in my opinion to remain as classed. Without a fresh record of survey until the completion of the survey as stated above.

Office Fee (if chargeable) per Scale II, Sec. 27	£	:	18.	Fees applied for,
Survey Fee (per Section 28)	£	:	18.	
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	:	18.	Received by me,
Travelling Expenses (if chargeable)	£	:	18.	
Second Surveyor's Fee (if any)	£	:	18.	

* Is Certificate now required?

Committee's Minute

Character assigned

PC No. 1

TUES. 6 NOV 1894

Deferred for
comple. of No.

FRIDAY 14 DEC 1894

© 2019



Lloyd's Register
Foundation
LON703 0342