

Sent to Chief Surveyors 19.12.94.

Received from Chief Surveyors

No. 3 SURVEY PARTLY HELD.

VESSEL'S NAME

Im S.S. "Carib"

Report

Lon. No. 5604

The remarks of the Chief Surveyor are desired on this Case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/8/92.)

Then due

9-94

When proposed to be completed


Not stated.

Portion of Survey held, &c.

S.S.No.3 part now held by the examination of the holds, ~~the~~ forward cross bunker, and peak, poop and fore-castle side plating under side lights, sluices, and watertight doors, and the testing of double bottom in holds and cross bunkers.

One fore-castle side plate repaired: several brackets to lower deck stringer in cross bunker, and part ceiling renewed. To compensate for the waisting of frames in forward cross bunker, a web frame is to be fitted, and damage to the bunker bulkhead repaired before the survey is completed.

It is submitted the vessel appears worthy to remain classed 100A1, record of survey and notation of S.S.No.3 being deferred until the completion of the same.



© 2019

C. J. M.  
Lloyd's Register  
Foundation

LON704-0080