

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 31/12/1894

When handed in at Local Office 31/12/1894

Port of London

No. in Reg. Book. Survey held at London
on the Wood, Iron or Steel S.

Date, First Survey

197

15/10/1874 Last Survey

D 18/12/1894

Carbet Castle

No. of Visits

1

Master

C. W. H. Johanning

YEAR.

1875

MONTH.

7

Page 53-53

TONNAGE: - 1657

Built at Sunderland

Master

C. W. H. Johanning

YEAR.

1875

MONTH.

7

GROSS 1640

UNDER Dk 1469

NET 1585

Owners Q. W. H. Johanning

Owners' Address

(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock Dugout

Name of Dock Commercial

Destined Voyage Sydney

WB=DBa tons; f tons; uE&B tons; CellDB tons;

FPT tons; APT tons; MT tons;

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides

of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,

girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 11856 Port Cff

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the

cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs

on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes;

and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the

replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles

should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment

Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS OR EXAMINATION AS PER RULE, FOR Condition

Condition

This steamer vessel was placed in dry dock

the bottom examined cleaned & recoated.

the rudder lifted & plates bushed

The main deck examined all the graving

pieces removed, the defective bolts renewed

the deck caulked & made efficient. The

graving pieces replaced.

The owner contemplates renewing this deck

on her return to the United Kingdom

from the present voyage.

SUMMARY OF DAMAGE REPAIRS:—

Plates, Fairied or Repaired:

Frames, ditto.

Plates, Renewed:

Frames, ditto.

Other Repairs

PRESENT CONDITION OF THE Vessel

Decks Good

Waterways

Coamings

Up'r Dk. Beams & Fastenings

Low'r Dk. Beams & Fastenings

Plating

Hull

Bolts or Rivets

Breasthooks & Jambeens

Transoms, Postures, & Gratings

Timbers of Frame at the openings

Ditto ditto at other places

Keelsons

Gangs, Stringers

Saddles

Ceiling

Cement on Asphalt

Tanks

(Steel strengthened)

Caulking of Bot'm, Dk, & Wat'rwy's.

Good

Good