

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 17th Jan 1895 When handed in at Local Office 18th Jan 1895 Port of London

No. in Reg. Book 159 Survey held at London Date, First Survey 12th Jan Last Survey 15th Jan 1895

on the Wood, Iron or Steel S.S. "Channmore" Master Campbell

TONNAGE:- Built at Barrow By whom Barrow S.B.C. When 1882. 7

GROSS 3377 Owners W. Johnston & Co. Port belonging to Barrow

UNDER DEK 2510 Owners' Address

NET 2215 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock 2nd 1894 Name of Dock Royal Albert Destined Voyage Boston

WB=Deba tons; f tons; uE&B tons; Cell DB tons; FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 56019 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Keel and bottom examined in dry dock, and the bottom cleaned and recoated.

(S.S. No. 3 completed by London Rpt 56019)

SUMMARY OF DAMAGE REPAIRS:—Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE Doubling Plates under Sounding Pipes

Decks Keel Transoms, Pointers, & Crutches

Waterways Timbers of Frame at the openings

Coamings Ditto ditto at other places

Up'r Dk. Beams & Fastenings Keelsons

Low'r Dk. Beams & Fastenings Clamps, Shelves & Stringers

Plating Ceiling

Planking Cement on Asphalt

Teacails or Rivets Tanks

Breasthooks & Stemson Caulking of Bot'm, D'k, & Wat'rw'ys

Copper, or Y.M. (State if on Fell.)

Rudder

Windlass & Capstan

Pumps

Engine Room Skylights

Coal Bunker, Open'gs, Lids, &c.

Scuppers

Cargo & Main H'tch'w'ys

Hatches

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length size

Rule length size

Hawsers & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed.

with record 1. 95.

Office Fee (if chargeable) per Scale II., Sec. 27

Survey Fee (per Section 28)

Special Damage or Repair Fee (if any) (per Sec. 28.)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

*Is Certificate now required?

Committee's Minute

Character assigned


100A1 Along dk. with f&b

2 Mc 3,94 ss. No. 3-11,94

In a Report also sent now on the Machinery of the Ship If not, state whether, and when, one will be sent?

* Certificate, if required, to be sent to

Form No. 2 for Repairs, 205-5000.—17/12/94.—Transfer Int. (The Surveyors are requested not to write on or below the space for Committee's Minute.)



© 2019 Lloyd's Register Foundation