

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 20th May 1895 When handed in at Local Office 18th May 1895 Port of London
No. in Reg. Book 691 Survey held at London Date, First Survey 14th May Last Survey 15th May 1895
on the Wood, Iron or Steel *See Minnesota* (No. of Visits 2) Master Cannon

TONNAGE: Built at Belfast By whom Harland & Wolff When 1887
GROSS 3216 Owners Atlantic Transport Co Port belonging to London
UNDER DEK 2988 Owners' Address
NET 2080 (if not already recorded in Appendix to Register Book.)
Surveyed Afloat or in Dry Dock? Name of Dock Millwall Destined Voyage American
WB=DBA tons; f tons; u&B tons; Cell DB tons; }
FPT tons; APT tons; MT tons. }

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 5942 Port LWS
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Years assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A1 5.94 * LMC 10.93 BS 2.95
SS LWS No 3-5.94
Shelter dk. for cattle with freeboard
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage

See Swansea report no 5942 in which three shell plates are reported as indented & a beam knee is bent—These have now been repaired.
The indented shell plate on Star^d side has been removed & replaced & replaced. The two indented plates on Port side have both been repaired in place. The damaged beam knee has been repaired, and it & an adjacent one riveted.
The bottom has been examined in dry dock it is in good condition & has been cleaned & coated.

SUMMARY OF DAMAGE REPAIRS: 3 Plates, Painted or Repaired; ✓ Frames, ditto. ✓ Plates, Renewed; ✓ Frames, ditto. Other Repairs.			
PRESENT CONDITION OF THE Doubling Plates under Sounding Pipes not seen			
Decks good	Transoms, Pointers, & Crutches	Copper, or Y.M. (State if on felt.)	Hatches good
Waterways	Timbers of Frame at the openings	When put on, Month Year	Boats
Coamings	Ditto ditto at other places	Rudder good	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings not seen	Keelsons	Windlass & Capstan	Condition, how ascertained from Dk
Low'r Dk. Beams & Fastenings	Clamps, Shelves & Stringers	Pumps not tried	Sails not seen
Plating good	Salting (State if examined.)	Engine Room Skylights good	Equipment letter no
Planking	Ceiling	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of 3015 2k
Treenails or Rivets	Cement or Asphalt (State which.)	Scuppers	Cables (State if now ranged) no
Breasthooks & Sternson not seen	Tanks (State if now tested.)	Cargo & Main H'tch'w'ys	„ length size
	Caulking of Bot'm, D'k, & Wat'r'w'ys good		„ Rule length size
			Hawser & Warps good
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 9,91,” or “to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c.”
As far as seen this vessel is now in good & efficient condition & is eligible in my opinion to remain as classed with record of survey 5.95

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for, 18.
Survey Fee (per Section 28) £ : : Received by me, 18.
Special Damage or Repair Fee (if any) (per Sec. 25.) £ : :
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :
*Is Certificate now required?
Committee's Minute FRI 24 MAY 1895
Character assigned 100 A1
Shelter deck for cattle with freeboard
A Campbell Holmes.
Surveyor to Lloyd's Register of British & Foreign Shipping.
© 2019 Lloyd's Register Foundation
LON705-0243