

WED 22 MAY 1895

(Received at London Office

18

No.

56546

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 20-5-95 When handed in at Local Office 21-5-95 Port of London

No. in Reg. Book Survey held at London Date, First Survey 15-5-95 Last Survey 18-5-1895

on the Wood, Iron or Steel S. Waitroa, now called Master M. B. Thies

TONNAGE:— Built at Newcastle By whom Winnipeg

GROSS 1057 Owners C. Zernichow

UNDER DK. 885 Owners' Address Christiania

NET 1015 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Horseferry Destined Voyage Udkersvall

WB=DDa tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 184 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified 3 ft. 10 1/2 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

This vessel was placed in Horseferry Dry Dock for examination of bottom for change of owners, but no application was made for survey.

The bottom was cleaned and recoated, the rudder lifted and pintles bushed, the head and stern pumps sea cocks overhauled.

The tonnage will probably altered, I have arranged that the new Register to be produced at this office in order that any modification may be noted, and inserted in the Register Book

SUMMARY OF DAMAGE REPAIRS:— Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE Doubling Plates under Sounding Pipes not seen

Decks Good Transoms, Decks, & Grates good

Waterways Timbers of Frame at the openings

Coamings Ditto ditto at other places

Up'r Dk. Beams & Fastenings Keelsons

Low'r Dk. Beams & Fastenings Clamps, Shells & Stringers

Plating Ceiling

Planking Cement on Deck

Second Deck Rivets Tanks

Breasthooks Caulking of Bot'm, Dk, & Wat'rwys

Copper, or Lead

Hatches Good

Boats

Masts, Yards, &c.

Condition, how ascertained from Dk

Sails good

Equipment letter 2

Anchors, No. of 3 B-18-2K

Cables (State if now ranged) no

length size

Rule length size

Hawsers & Warps good

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptn 91, &c."

This vessel now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed with a fresh record of survey Lon 5/95

Office Fee (if chargeable) per Scale II., Sec. 27

Survey Fee (per Section 28)

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for

Received by me

Is Certificate now required?

Committee's Minute

Character assigned

FRI 24 MAY 1895

100 A1

Edward G. Turner

Surveyor to Lloyd's Register of British & Foreign Shipping.

LLOYD'S REGISTER

© 2019

Lloyd's Register

Foundation

LON 705-0247