

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report *4th June 95* When handed in at Local Office *18* Port of *London*  
No. in Reg. Book *503* Survey held at *London* Date, First Survey *5th June 1895* and Last Survey *5th June 1895*  
on the Machinery of the *Wood, Iron or Steel* *S. S. "Chickahominy"* Master *S. Farnaux*  
Tonnage Gross *2875* Net *1821* Vessel built at *West Hartlepool* By whom *Furness, Withy & Co* When *1893* YEAR. MONTH. *11*  
Registered *412* Engines made at *Do.* When *1893* Boilers, when made (Main) *1893* (Donkey) *1893*  
Horse Power *400* Owners *Chesapeake Ohio S. S. Co.* Port *W. Hartlepool* Voyage *Newport News*  
No. of Main Boilers *one* No. of Donkey Boilers *one* If Surveyed *Afloat or in Dry Dock* *Royal Albert dry dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
Steam Pressure in Main Boilers *160* in Donkey Boilers *80*

Last Survey No. *100 A 1.* Port *London*  
Particulars of Examination and Repairs (if any) *Condition*  
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*  
Do. " Donkey " " " *No*  
If this was not done, state for what reasons? *Not due for survey.*  
And what parts of the Boilers could not be thus thoroughly examined? *✓*  
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *No*  
Did the Surveyor examine the Safety Valves of the Main Boiler? *No*  
At what pressure were they afterwards adjusted under steam? *Not adjusted*  
Did the Surveyor examine the Safety Valves of Donkey Boiler? *No*  
To what pressure were they afterwards adjusted? *Not adjusted*

If the Survey is not complete state what arrangements have been made for its completion? *Complete.*  
*Propeller and pea-connection fastenings examined and found in order.*

General Observations, Opinion, and Recommendation: *This vessel's machinery, so far as seen, is in safe working condition and eligible, in my opinion, to remain as classed without further record of survey.*

Office or Registration Fee (per Sec. 27) £ : / Fees applied for  
Survey Fee (per Section 28) £ : / 18  
Special Damage Fee (per Section 28) £ : /  
Travelling Expenses (if chargeable) £ : / Received by me, *L. Elliott*  
18  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required  
Committee's Minute *TUES 11 JUN 1895*  
Assigned *As now*



It is submitted that  
this vessel is eligible to  
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

A R R  
8.6.95

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation